



Product Change Notification

107983 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jcb.ijkk@intel.com

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107983 - 01
Change Title: DP965LT, PCN 107983-01, Product Design, BIOS Update to implement enhanced features, add alternate component, and revert back to Marvell PATA B1 stepping, Reason for Revision: Wrong dash numbers in pre and post change
Date of Publication: March 04, 2008

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Dec 27, 2007
---	--------------

Description of Change to the Customer:

Reason for Revision: Wrong dash numbers in pre and post change

BIOS is being updated to MQ96510J,86A.1715 to incorporate the new Intel® System Recovery Tool BIOS. Please refer to the release notes posted at <http://developer.intel.com/products/motherboard/DP965LT/tools.htm>

Alternate FET driver added from ON SEMICONDUCTOR for location U2VR, U3VR, U4VR, U5VR.

Previous ECO to change the Marvell PATA at EU1PT, stepping from B1 to B2 had not yet been implemented by factory. This change has been postponed.

Customer Impact of Change and Recommended Action:

It is recommended that customers evaluate this new BIOS to ensure a smooth transition.

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. Intel is not recommending additional qualification of these changes on platforms received from Intel. This change is not expected to cause a

change to the Microsoft* Windows* operating system's software driver stack. No expected OS image change.

Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change AA	Post Change AA
BLKDP965LTCK 888277	888277	D41694-301	D41694-302
BOXDP965LTCK 888278	888278	D41694-301	D41694-302

PCN Revision History:

Date of Revision:

December 10, 2007

March 4, 2008

Revision Number:

00

01

Reason:

Originally Published PCN

Wrong dash numbers in pre and post change