



Product Change Notification

109838 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: <mailto:asmo.pcn@intel.com>

Asia Pacific Contact: <mailto:apacgccb@intel.com>

Europe Email: <mailto:eccb@intel.com>

Japan Email: <mailto:jccb.ijkk@intel.com>

Copyright © Intel Corporation 2010. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109838 - 01
Change Title: DH55TC and DH55HC, PCN 109838-01, Product Material, Updated the Intel(R) Express Installer DVD. Reason for Revision: TA numbers were incorrect on the original PCN. This revision has the correct TA numbers.
Date of Publication: February 26, 2010

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Mar 12, 2010
---	--------------

Description of Change to the Customer:

Reason for Revision: TA numbers were incorrect on the original PCN. This revision has the correct TA numbers.

Intel has implemented the following change:

Fixed an installation issue on the Intel Express Installer DVD with the ESET Smart Security 4* software.

Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability, or functional implications to our customers. Intel is not recommending additional qualification of these changes on desktop boards received from Intel.

Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change TA	Post Change TA
BOXDH55TC	903541	E71479-102	E71479-103
BLKDH55TC	903542	E71477-102	E71477-103
BOXDH55HC	903545	E71482-101	E71482-102
BLKDH55HC	903546	E71481-101	E71481-102

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
February 12, 2010	00	Originally Published PCN
February 26, 2010	01	TA numbers were incorrect on the original PCN. This revision has the correct TA numbers.