



# Product Change Notification

## 107615 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #: 107615 - 00**

**Change Title: D201GLY, PCN 107615-00,  
Product Design, Adding alternate  
parts and BIOS update**

**Date of Publication: June 04, 2007**

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Jun 21, 2007
---	--------------

## Description of Change to the Customer:

New SPI part and DIMM connector has been added as alternate part. Latest BIOS will be updated to support the new SPI chip and fix the BIOS corruption issue.

## Customer Impact of Change and Recommended Action:

This board change is not expected to cause a change to the Microsoft\* Windows\* operating system's software driver stack. This change are being thoroughly evaluated to ensure that there is no quality, reliability or functional implications to our customers. NO additional qualification is recommended for this change on platforms received from Intel.

## Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change AA	Pre Change PBA	Post Change AA	Post Change PBA
LAD201GLYLT 887701	887701	D78099-303	D78100-303	D78099-304	D78100-304
LAD201GLYL 887702	887702	D76864-302	D81208-302	D76864-303	D81208-303
BLKD201GLYL 887958	887958	D81205-302	D81208-302	D81205-303	D81208-303
BOXD201GLYL 887961	887961	D81205-302	D81208-302	D81205-303	D81208-303

**Reference Documents / Attachments:**

**Document:**

**Location #:**

**PCN Revision History:**

**Date of Revision:**

June 4, 2007

**Revision Number:**

00

**Reason:**

Originally Published PCN