



# Product Change Notification

## 107859 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 107859 - 00  
**Change Title:** The Intel PRO/MT Dual Port Server Adapter (Double Barrow), PRO/1000 MF Dual Port Server Adapter (Double Eldridge), PRO/1000 MT Server Adapter (Everson), PRO/1000 MF Server Adapter (Baldry), and PRO/1000 MF Server Adapter LX (Baldry LX) (Retail & OEM Generic Adapters)

**PCN 107859-00**

**Label**

**UL Logo Label Addition to the Front of the Printed Board**

**Date of Publication:** September 6, 2007

## Key Characteristics of the Change:

Label

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Sep 17, 2007
---	--------------


## Description of Change to the Customer:

The Intel PRO/MT Dual Port Server Adapter (Double Barrow), PRO/1000 MF Dual Port Server Adapter (Double Eldridge), PRO/1000 MT Server Adapter (Everson), PRO/1000 MF Server Adapter (Baldry) and PRO/1000 MF Server Adapter LX (Baldry LX) (Retail & OEM Generic Adapters) will undergo the following change:

Intel is updating our UL logo which is placed on the primary (front) side of the Printed Board (PB). The slight space between the two letters will be closed. There is no change in our UL Certification. This update logo label will be placed over the previous silk screened label. **See picture of the updated UL Logo label below.**

The previous version of the UL Logo was silk screened on the primary side of the PB, this logo included a space small space between the two letters. **See picture of the previous UL Logo below.**


**Old UL logo, silk screened onto the printed board.  
Note slight space between the two letters (example only)**



The New UL logo label, will be placed as a label over the original silk screened marking. Note the space between the two letters is now closed.

New UL logo label

Note slight space between the two letters is now closed (example only)



### **Customer Impact of Change and Recommended Action:**

This change will have no impact to the customer, and no customer action is required, except to note this change and expect the product to start shipping with updated UL logo after September 10, 2007.

Customers should expect to receive mixed inventory until current inventory levels are depleted.

As a result of this change, the TA (Top Assembly) and PBA (Printed Board Assembly) numbers will roll as noted in the Affected Products Table within this product change notification.

## Products Affected / Intel Ordering Codes:

Product Family	Product Code	MM#	Old TA	New TA	Old PBA	New PBA
PRO/1000 MT Dual Port Server Adapter (Double Barrow) OEM G2 20 pak	PWLA8492MTG2P20	853671	C40215-004	C40215-005	C36649-003	C36649-004
PRO/1000 MT Dual Port Server Adapter (Double Barrow) OEM G2 LP 20 pak	PWLA8492MTG2L20	853670	C40222-004	C40222-005	C36650-003	C36650-004
PRO/1000 MT Dual Port Server Adapter (Double Barrow) OEM G3 20 pak	PWLA8492MTG3P20	856114	C48910-003	C48910-004	C49882-003	C49882-004
PRO/1000 MT Dual Port Server Adapter (Double Barrow) OEM G3 LP 20 pak	PWLA8492MTG3L20	856115	C48911-003	C48911-004	C49883-003	C49883-004
PRO/1000 MT Dual Port Server Adapter (Double Barrow) Retail Single	PWLA8492MT	844143	A85400-007	A85400-008	C41421-004	C41421-005
PRO/1000 MT Dual Port Server Adapter (Double Barrow) Retail Blk 5 pak	PWLA8492MTBLK5	847743	A85399-006	A85399-007	C41421-004	C41421-005
PRO/1000 MF Dual Port Server Adapter (Double Eldridge) OEM G3 20 pak	PWLA8492MFG3P20	856117	C48913-003	C48913-004	C49735-003	C49735-004
PRO/1000 MF Dual Port Server Adapter (Double Eldridge) OEM G3 LP 20 pak	PWLA8492MFG3L20	856116	C48912-003	C48912-004	C49736-003	C49736-004
PRO/1000 MF Dual Port Server Adapter (Double Eldridge) Retail Single	PWLA8492MF	844141	A85401-007	A85401-008	C41300-004	C41300-005
PRO/1000 MF Dual Port Server Adapter (Double Eldridge) Retail Blk 5 pak	PWLA8492MFBLK5	847744	A85398-007	A85398-008	C41300-004	C41300-005
PRO/1000 MT Server Adapter (Everson) OEM G1 20 pak	PWLA8490MTG1P20	844795	A85393-004	A85393-005	C48637-003	C48637-004
PRO/1000 MT Server Adapter (Everson) OEM G1 LP 20 pak	PWLA8490MTG1L20	844794	A85391-004	A85391-005	C49881-003	C49881-004
PRO/1000 MT Server Adapter (Everson) Retail Single	PWLA8490MT	845956	A85402-007	A85402-008	C36840-005	C36840-006
PRO/1000 MT Server Adapter (Everson) Retail Blk 5 pak	PWLA8490MTBLK5	847742	A90837-006	A90837-007	C36840-005	C36840-006
PRO/1000 MF Server Adapter (Baldry) OEM G1 20 pak	PWLA8490MFG1P20	844793	A85394-004	A85394-005	C48615-003	C48615-004
PRO/1000 MF Server Adapter (Baldry) OEM G1 LP 20 pak	PWLA8490MFG1L20	844792	A85390-004	A85390-005	C49739-003	C49739-004
PRO/1000 MF Server Adapter (Baldry) Retail Single	PWLA8490MF	845954	A85395-007	A85395-008	C36851-004	C36851-005
PRO/1000 MF Server Adapter (Baldry) Retail Blk 5 pak	PWLA8490MFBLK5	847741	A90839-006	A90839-007	C36851-004	C36851-005
PRO/1000 MF Server Adapter LX (Baldry LX) OEM G1 20 pak	PWLA8490LXG1P20	845712	A90851-004	A90851-005	C49741-003	C49741-004
PRO/1000 MF Server Adapter LX (Baldry LX) Retail Single	PWLA8490LX	845952	A90853-007	A90853-008	C37793-004	C37793-005
PRO/1000 MF Server Adapter LX (Baldry LX) Retail Blk 5 pak	PWLA8490LXBLK5	847740	A90852-006	A90852-007	C37793-004	C37793-005

**Reference Documents / Attachments:**

**Document:**

**Location #:**

**PCN Revision History:**

**Date of Revision:**

**Revision Number:**

**Reason:**

September 6, 2007

00

Originally Published PCN