



# Product Change Notification

## 111117 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

Asia Pacific Contact: [apacgccb@intel.com](mailto:apacgccb@intel.com)

Europe Email: [eccb@intel.com](mailto:eccb@intel.com)

Japan Email: [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2011. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

<b>Change Notification #:</b>	<b>11117-00</b>
<b>Change Title:</b>	<b>Intel Ethernet Server Adapters I340-T2, I340-T4 &amp; I340-F4, E1G42HTG1P20/E1G44HT/E1G44HTBLK/E1G44HTG1P20/ E1G44HF/E1G44HFBLK/E1G44HFG1P20 (Bartonville DT/QT/QF OEM generic/Retail)</b>  <b>PCN 11117-00</b>  <b>Label</b>  <b>OUI block change</b>
<b>Date of Publication:</b>	<b>November 14, 2011</b>

<b>Key Characteristics of the Change:</b>
Label

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Nov 24, 2011
---	--------------


## Description of Change to the Customer:

The Intel Ethernet Server Adapters I340-T2, I340-T4 & I340-F4, E1G42HTG1P20/E1G44HT/E1G44HTBLK/E1G44HTG1P20/E1G44HF/E1G44HFBLK/E1G44HFG1P20 (Bartonville DT/QT/QF OEM generic/Retail) will undergo the following changes:

**OUI Block change:** Past run rates have caused the available blocks of MAC addresses assigned to run out. The OUI Block 00-1B-21 has hit the low water mark, the new OUI Block will be 90-E2-BA.

As a result of this change, the PBA (printed board assembly) and TA (top assembly) numbers will roll as noted in the affected products table within this PCN notice. If the PBA/TA numbers are printed on any product or box labels, those will show the PBA/TA dash roll as well.

**3n1 label change:** The 3n1 label will change to reflect the new OUI Block number and PBA# dash roll (printed board assembly), as show in the picture below. The 3n1 label is placed on the Front side of the Printed Board. (picture example only)



### Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers.

Customers can expect to receive mixed inventory until current inventory levels are depleted.

### Products Affected / Intel Ordering Codes:

Product Name	Product Code	MM#	OLD TA	NEW TA	OLD PBA	NEW PBA
Intel Ethernet Server Adapter I340-T4 Bartonville QT Retail	E1G44HT	904198	E76877-003	E76877-004	E84075-003	E84075-004
Intel Ethernet Server Adapter I340-T4 Bartonville QT Retail Blk 5-pak	E1G44HTBLK	904223	E80225-003	E80225-004	E84075-003	E84075-004
Intel Ethernet Server Adapter I340-T4 Bartonville QT OEM generic 20-pak	E1G44HTG1P20	904267	E80231-005	E80231-006	E68891-015	E68891-016
Intel Ethernet Server Adapter I340-F4 Bartonville QF Retail	E1G44HF	904245	E80229-003	E80229-004	E97466-003	E97466-004
Intel Ethernet Server Adapter I340-F4 Bartonville QF Retail Blk 5-pak	E1G44HFBLK	904247	E80230-003	E80230-004	E97466-003	E97466-004
Intel Ethernet Server Adapter I340-F4 Bartonville QF OEM generic 20-pak	E1G44HFG1P20	904279	E80236-004	E80236-005	E96895-007	E96895-008
Intel Ethernet Server Adapter I340-T2 Bartonville DT OEM generic 20-pak	E1G42HTG1P20	904277	E80235-003	E80235-004	E79938-011	E79938-012

### PCN Revision History:

Date of Revision:	Revision Number:	Reason:
November 14, 2011	00	Originally Published PCN