



Product Change Notification

109081 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109081 - 01
Change Title: Intel(R) Workstation Board S5000XVN, PCN 109081-01, Product Design, Update BIOS, Reason for Revision: Update BIOS version, Add SMS3.1 and change customer receive date
Date of Publication: February 09, 2009

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Mar 20, 2009
---	--------------

Description of Change to the Customer:

Reason for Revision: Update BIOS version, Add SMS3.1 and change customer receive date

Intel(R) is updating the board BIOS to version R0096. This updated BIOS release includes fixes for the Machine Check Exception (MCE) issue reported on a relatively small number of S5000XVN baseboards when using some Intel(R) Xeon(R) 5400 Series Processors.

The Intel(R) Server Management Software DVD version 3.1 is added to the boxed board products.

The attention document is also being updated.

Customer Impact of Change and Recommended Action:

Intel recommends customers update to BIOS R0096. The latest software package can be obtained at <http://support.intel.com/support/motherboards/server/s5000xvn/index.htm>

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change MM#	Post Change TA	Post Change PBA
S5000XVNSASR	900391	E12276-005	E11034-201	901765	E12276-006	E11034-202
S5000XVNSATAR	900392	E12278-005	E11030-201	901766	E12278-006	E11030-202
BB5000XVNSASR	900531	E12388-201	E11034-201	901725	E12388-202	E11034-202
BB5000XVNSATAR	900533	E12391-201	E11030-201	901726	E12391-202	E11030-202

Reference Documents / Attachments:

Document: **Location #:**

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
December 4, 2008	00	Originally Published PCN
February 9, 2009	01	Update BIOS version, Add SMS3.1 and change customer receive date