



Product Change Notification

108406 - 02

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jcb.ijkk@intel.com

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 108406 - 02
Change Title: DG35EC, PCN 108406-02, Product Design, BIOS Update and capacitor addition, Reason for Revision: Add link for Technical Assistance
Date of Publication: May 02, 2008

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:


Date Customer Must be Ready to Receive Post-Conversion Material:	May 08, 2008
---	--------------

Description of Change to the Customer:

Reason for Revision: Add link for Technical Assistance

Update BIOS to ECG3510M.86A.0072.
Please refer to the release notes posted at
<http://developer.intel.com/products/motherboard/DG35EC/tools.htm>

As part of Intel's continuing commitment to enhance product quality and reliability, all Intel desktop boards DG35EC are now being manufactured with an improved PATA controller design. A 10uF capacitor has been added to locations JMB4 and JMB6 respectively as shown in figure below.



For more technical assistance, please refer to Intel Desktop Board DG35EC support web page at:
<http://www.intel.com/support/motherboards/desktop/DG35EC/index.htm>

Customer Impact of Change and Recommended Action:

It is recommended that customers evaluate this new BIOS to ensure a smooth transition.

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. Intel is not recommending additional qualification of these changes on platforms received from Intel. This change is not expected to cause a change to the Microsoft* Windows* operating system's software driver stack.

Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change AA	Post Change AA
BOXDG35EC	896207	E29266-202	E29266-203
BLKDG35EC	896208	E29266-202	E29266-203
LADG35EC	897336	E37012-202	E37012-203
BOXDG35ECC	898194	E39017-202	E39017-203
BLKDG35ECC	898195	E39017-202	E39017-203

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
April 24, 2008	00	Originally Published PCN
April 28, 2008	01	Capacitors added
May 2, 2008	02	Add link for Technical Assistance