



Product Change Notification

#112805- 00

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia/PRC Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2013. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 112805-00
Change Title: Selected Intel® Pentium® Processors, Intel Celeron® Processors and Intel Atom™ Processors, PCN 112805-00, Manufacturing Site, Country of Origin Label Adding Vietnam
Date of Publication: December 24, 2013

Key Characteristics of the Change:
Manufacturing Site

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	December 24, 2013
-------------------------------------------------------------------------	-------------------

Description of Change to the Customer:

In order to ensure a continuous supply of the Intel® Pentium® Processors, Intel Celeron® Processors and Intel Atom™ Processors listed in the "Products Affected" Table below, Intel will now manufacture these products using another Intel qualified assembly site. The new site is located in Vietnam. The new manufacturing site has been certified equivalent (form, fit, function, and reliability) for the affected products and technologies of this change.

Due to this change, the "ASSEMBLED IN (Country)" on the Intermediate Box Label, see example below, will now include Vietnam. All material and equipment will remain the same.

(P) CUST PROD:

(V) SUPPLIER: 04195 INTEL

(1P) IPN: FH8065301455104

(S) SPEC: S R1LM (30P) MM#: 931090

(1T) LOT: FPO NUMBER (Q) QTY: 12345 (9D) DATE: 1213

(1T) LOT: (Q) QTY: (9D) DATE:

RoHS COMPLIANT, e1

(1B) BOX: RLX00026

MAX REFLOW 260 °C
TEMP

LEVEL 3 HOURS 168
BAG SEAL DATE 19DEC13

ASSEMBLED IN VIETNAM

Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers for this change. Customers may see products from all assembly sites. Customers may want to notify their receiving department of the additional Country of Origin marking.

Products Affected / Intel Ordering Codes:

Marketing Name	Processor#	Frequency	Stepping	Product Code	S-Spec	MM#
Intel® Pentium® Processor	J2850	2.41 GHZ	B1	FH8065301455104	S R1H4	930734
Intel® Celeron® Processor	J1850	2.0 GHZ	B1	FH8065301455200	S R1H5	930735
Intel® Celeron® Processor	J1750	2.41 GHZ	B1	FH8065301562600	S R1H6	930736
Intel® Pentium® Processor	N3510	2.0 GHZ	B1	FH8065301546301	S R1HP	930817
Intel® Celeron® Processor	N2910	1.6 GHZ	B1	FH8065301546402	S R1HQ	930818
Intel® Celeron® Processor	N2810	2.0 GHZ	B1	FH8065301564501	S R1HR	930819
Intel® Celeron® Processor	N2805	1.46 GHZ	B1	FH8065301564600	S R1HS	930820
Intel® Atom Processor	E3840	1.91 GHZ	B1	FH8065301487704	S R1HT	930823
Intel® Atom Processor	E3823	1.75 GHZ	B1	FH8065301487905	S R1HU	930824
Intel® Atom Processor	E3822	1.46 GHZ	B1	FH8065301542202	S R1HV	930825
Intel® Atom Processor	E3821	1.33 GHZ	B1	FH8065301567300	S R1HW	930826
Intel® Atom Processor	E3810	1.46 GHZ	B1	FH8065301567400	S R1HX	930827
Intel® Pentium® Processor	J2850	2.41 GHZ	B2	FH8065301455104	S R1LM	931090
Intel® Celeron® Processor	J1850	2.0 GHZ	B2	FH8065301455200	S R1LN	931092
Intel® Celeron® Processor	J1750	2.41 GHZ	B2	FH8065301562600	S R1LP	931094
Intel® Atom Processor	E3840	1.91 GHZ	B2	FH8065301487704	S R1LQ	931105
Intel® Atom Processor	E3823	1.75 GHZ	B2	FH8065301487905	S R1LR	931106
Intel® Atom Processor	E3810	1.46 GHZ	B2	FH8065301567400	S R1LU	931109
Intel® Pentium® Processor	N3510	2.0 GHZ	B2	FH8065301546301	S R1LV	931112
Intel® Celeron® Processor	N2910	1.6 GHZ	B2	FH8065301546402	S R1LW	931114
Intel® Celeron® Processor	N2810	2.0 GHZ	B2	FH8065301564501	S R1LX	931116
Intel® Celeron® Processor	N2805	1.46 GHZ	B2	FH8065301564600	S R1LY	931118
Intel® Atom Processor	E3815	1.46 GHZ	B3	FH8065301567411	S R1RA	932048
Intel® Atom Processor	E3825	1.33 GHZ	B3	FH8065301567311	S R1RB	932049
Intel® Atom Processor	E3826	1.46 GHZ	B3	FH8065301542213	S R1RC	932050
Intel® Atom Processor	E3827	1.75 GHZ	B3	FH8065301487916	S R1RD	932051
Intel® Atom Processor	E3845	1.91 GHZ	B3	FH8065301487715	S R1RE	932052
Intel® Pentium® Processor	J2900	2.41 GHZ	B3	FH8065301614903	S R1SB	932479
Intel® Celeron® Processor	J1900	2.0 GHZ	B3	FH8065301615009	S R1SC	932481
Intel® Celeron® Processor	J1800	2.41 GHZ	B3	FH8065301615103	S R1SD	932483
Intel® Pentium® Processor	N3520	2.17 GHZ	B3	FH8065301616103	S R1SE	932485
Intel® Celeron® Processor	N2920	1.86 GHZ	B3	FH8065301616203	S R1SF	932490
Intel® Celeron® Processor	N2820	2.13 GHZ	B3	FH8065301616603	S R1SG	932492
Intel® Celeron® Processor	N2806	1.6 GHZ	B3	FH8065301616703	S R1SH	932494
Intel® Celeron® Processor	N2815	1.86 GHZ	B3	FH8065301619509	S R1SJ	932579

PCN Revision History:

Date of Revision:

December 24, 2013

Revision Number:

00

Reason:

Originally Published PCN