



Product Change Notification

109445 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109445 - 00
Change Title: Intel® Server Systems SR2600 and SR2625, PCN 109445-00, Product Design, Updating Power Supply Firmware to address errata
Date of Publication: June 24, 2009

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Aug 14, 2009
---	--------------

Description of Change to the Customer:

The firmware on the power supply is being updated to address errata #25. Please see the SR5520UR Monthly Specification Update posted to Intel's support website for more information.

This change is occurring concurrently with PCNs 109423 and 109436.

Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
SR2600URLX	900988	E43324-004	E30692-006	E43324-005	E30692-007
SR2625URBRP	900989	E43325-004	E30692-006	E43325-005	E30692-007
SR2625URLX	900990	E43326-004	E30692-006	E43326-005	E30692-007
SR2600URBRP	901093	E43323-004	E30692-006	E43323-005	E30692-007
SR2600URBRPNA	901187	E43323-004	E30692-006	E43323-005	E30692-007
SR2625URBRPNA	901141	E43325-004	E30692-006	E43325-005	E30692-007
SR2625URLXNA	901129	E43326-004	E30692-006	E43326-005	E30692-007
SR2600URLXNA	901131	E43324-004	E30692-006	E43324-005	E30692-007

Reference Documents / Attachments:

Document: _____ **Location #:** _____

PCN Revision History:

Date of Revision: _____ **Revision Number:** _____ **Reason:** _____

