



# Product Change Notification

## 106825 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

Asia Pacific Contact: [apacgccb@intel.com](mailto:apacgccb@intel.com)

Europe Email: [eccb@intel.com](mailto:eccb@intel.com)

Japan Email: [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 106825 - 00  
**Change Title:** SC5300, PCN 106825-00, Product Design, 4HDD/6HDD Drive Bay SCSI HSBP HSC FW Update  
**Date of Publication:** November 14, 2006

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Dec 15, 2006
---	--------------

## Description of Change to the Customer:

A timing issue was identified with Boot Code 1.12 shipping on backplanes built with Firmware 1.14. In some cases this issue caused firmware update failures leaving the backplane in an undetermined state. New backplanes with the product TA's below will use Firmware 1.16 (Boot Code 1.13).

Firmware 1.16 only contains changes to the Boot Code to repair this issue; no changes were made to the Op Code.

Refer to TA-829-2 for more details.

## Customer Impact of Change and Recommended Action:

Customers may want to perform a standard level of validation on the new firmware.

## Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
FXX6SCSIBRD	880512	D50272-001	C53587-450	D50272-002	C53587-451
FXX4SCSIBRD	880547	D50280-001	C53589-450	D50280-002	C53589-451
SC5300AF2	880711	D50256-005		D50256-006	
SC5300AF2NA	881230	D50256-005		D50256-006	
AXX6SCSIDB	880535	D50274-002	C53587-450	D50274-003	C53587-451
AXX4SCSIDB	880536	D50278-002	C53589-450	D50278-003	C53589-451
AXX4SCSIDB0OEM	880549	D50281-002	C53589-450	D50281-003	C53589-451
AXX6SCSIDB0OEM	880552	D50282-002	C53587-450	D50282-003	C53587-451

## Reference Documents / Attachments:

**Document:**

**Location #:**

**PCN Revision History:**

**Date of Revision:**

November 14, 2006

**Revision Number:**

00

**Reason:**

Originally Published PCN