



Product Change Notification

107720 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107720 - 00

**Change Title: D201GLY, PCN 107720-00,
Product Material, New processor
stepping**

Date of Publication: July 09, 2007

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jul 26, 2007
---	--------------

Description of Change to the Customer:

Soldered down processor with new stepping (E-step) will be added as primary part for Intel Desktop Board D201GLY.

A new fan screw will be added to improve reliability.

Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. CDPG is not recommending additional qualification of these changes on platforms received from Intel. These board changes are not expected to cause a change to the Microsoft* Windows* operating system's software driver stack. No expected OS image change.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change AA	Pre Change PBA	Post Change AA	Post Change PBA
LAD201GLYLT 887701	887701	D78099-304	D78100-304	D78099-305	D78100-305
LAD201GLYL 887702	887702	D76864-303	D81208-303	D76864-304	D81208-304
BLKD201GLYL 887958	887958	D81205-303	D81208-303	D81205-304	D81208-304
BOXD201GLYL 887961	887961	D81205-303	D81208-303	D81205-304	D81208-304

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

July 9, 2007

Revision Number:

00

Reason:

Originally Published PCN