



# Product Change Notification

## 107645 - 03

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 107645 - 03  
**Change Title:** SR1500, SR1550 and SR2500 Based Systems, and Spares, PCN 107645-03, Product Design, Class 2, Bridgeboard Mechanical Design Revision, Reason for Revision: milestone date needs update  
**Date of Publication:** November 14, 2007

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

|   |              |
|---|--------------|
| <b>Date Customer Must be Ready to Receive Post-Conversion Material:</b> | Nov 30, 2007 |
|---|--------------|

## Description of Change to the Customer:

**Reason for Revision:** milestone date needs update

Intel is changing the taper of the fingers on the bridgeboard to ensure compatibility with future Intel boards and systems. This change will have no fit, form or functional impact to current products.

## Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers.

## Products Affected / Intel Ordering Codes:

| Pre Change Product Code | Pre Change MM# | Pre Change TA | Pre Change PBA | Post Change MM# | Post Change TA | Post Change PBA |
|-------------------------|----------------|---------------|----------------|-----------------|----------------|-----------------|
| FALBRIDGE               | 880519         | D43780-003    | D25543-401     | 880519          | D43780-004     | D25543-402      |
| ASR1500EESPR            | 880900         | D47695-004    | D25543-401     | 880900          | D47695-005     | D25543-402      |
| ASR2500EESPR            | 881265         | D43775-006    | D25543-401     | 881265          | D43775-007     | D25543-402      |
| ASR1550EESPR            | 881678         | D48158-003    | D25543-401     | 881678          | D48158-004     | D25543-402      |
| SR1500                  | 881037         | D47572-006    | D25543-401     | 881037          | D47572-007     | D25543-402      |
| SR1500NA                | 881460         | D47572-005    | D25543-401     | 881460          | D47572-006     | D25543-402      |
| SR2500                  | 881105         | D43689-012    | D25543-401     | 881105          | D43689-013     | D25543-402      |
| SR2500NA                | 881461         | D43689-012    | D25543-401     | 881461          | D43689-013     | D25543-402      |
| SR1550                  | 881737         | D48156-006    | D25543-401     | 881737          | D48156-007     | D25543-402      |
| SR1550NA                | 881752         | D48156-005    | D25543-401     | 881752          | D48156-006     | D25543-402      |
| SR1500AL                | 885480         | D47500-016    | D25543-401     | 885480          | D47500-017     | D25543-402      |
| SR1500ALNA              | 885482         | D47500-015    | D25543-401     | 885482          | D47500-016     | D25543-402      |
| SR1500ALR               | 891962         | D99976-002    | D25543-401     | 891962          | D99976-003     | D25543-402      |

|                |        |            |            |        |            |            |
|----------------|--------|------------|------------|--------|------------|------------|
| SR1500ALRNA    | 892025 | D99976-002 | D25543-401 | 892025 | D99976-003 | D25543-402 |
| SR1500ALSASR   | 891963 | E10101-002 | D25543-401 | 891963 | E10101-003 | D25543-402 |
| SR1500ALSASRNA | 892029 | E10101-002 | D25543-401 | 892029 | E10101-003 | D25543-402 |
| SR2500ALBRPR   | 891964 | E10104-002 | D25543-401 | 891964 | E10104-003 | D25543-402 |
| SR2500ALBRPRNA | 892030 | E10104-002 | D25543-401 | 892030 | E10104-003 | D25543-402 |
| SR2500ALLXR    | 891965 | E10105-002 | D25543-401 | 891965 | E10105-003 | D25543-402 |
| SR2500ALLXRNA  | 892032 | E10105-002 | D25543-401 | 892032 | E10105-003 | D25543-402 |
| SR2500ALOEMR   | 891966 | E10333-002 | D25543-401 | 891966 | E10333-003 | D25543-402 |
| SR2500ALOEMRNA | 892033 | E10333-002 | D25543-401 | 892033 | E10333-003 | D25543-402 |
| SR1550ALR      | 891970 | E10102-001 | D25543-401 | 891970 | E10102-002 | D25543-402 |
| SR1550ALRNA    | 892034 | E10102-001 | D25543-401 | 892034 | E10102-002 | D25543-402 |
| SR1550ALSASR   | 891967 | E10103-001 | D25543-401 | 891967 | E10103-002 | D25543-402 |
| SR1550ALSASRNA | 892046 | E10103-001 | D25543-401 | 892046 | E10103-002 | D25543-402 |

## Reference Documents / Attachments:

**Document:**

**Location #:**

## PCN Revision History:

**Date of Revision:**

**Revision Number:**

**Reason:**

August 1, 2007

00

Originally Published PCN

August 21, 2007

01

Availability date change

November 13, 2007

02

Bensley Refresh requests that  
product codes change accordingly.

November 14, 2007

03

milestone date needs update