



Product Change Notification

111212 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2011. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #:	111212 - 00
Change Title:	Intel Ethernet Server Adapters X520-T2, E10G42BT/BTG1P5 (Iron Pond Retail/OEM generic), Intel 10 Gigabit CX4 Dual Port Server Adapter, EXPX502CX4 (Cedar Cove Retail) and Intel 10 Gigabit XF SR Server Adapters, EXPX9501AFXSR/SRGP5 (Bellefontaine Retail/OEM generic) PCN 111212-00 Label OUI block change
Date of Publication:	December 19, 2011

Key Characteristics of the Change:

Label

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material: Jan 19, 2012


Description of Change to the Customer:

The Intel Ethernet Server Adapters X520-T2, E10G42BT/BTG1P5 (Iron Pond Retail/OEM generic), Intel 10 Gigabit CX4 Dual Port Server Adapter, EXPX502CX4 (Cedar Cove Retail) and Intel 10 Gigabit XF SR Server Adapters, EXPX9501AFXSR/SRGP5 (Bellefontaine Retail/OEM generic) will undergo the following changes:

OUI Block change: Past run rates have caused the available blocks of MAC addresses assigned to run out. The OUI Block 00-1B-21 has hit the low water mark, the new OUI Block will be 68-05-CA.

As a result of this change, the PBA (printed board assembly) and TA (top assembly) numbers will roll as noted in the affected products table within this PCN notice. If the PBA/TA numbers are printed on any product or box labels, those will show the PBA/TA dash roll as well.

3n1 label change: The 3n1 label will change to reflect the new OUI Block number and PBA# dash roll (printed board assembly), as show in the picture below. The 3n1 label is placed on the Front side of the Printed Board. (picture example only)



Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers.

Customers can expect to receive mixed inventory until current inventory levels are depleted.

Products Affected / Intel Ordering Codes:

Product Name	Product Code	MM#	OLD TA	NEW TA	OLD PBA	NEW PBA
Intel 10 Gigabit XF SR Server Adapter (Bellefontaine OEM generic 5-pak)	EXPX9501FXSRGP5	893132	E18471-006	E18471-007	E16791-006	E16791-007
Intel 10 Gigabit XF SR Server Adapter (Bellefontaine Retail)	EXPX9501AFXSR	893264	E22317-004	E22317-005	E18269-004	E18269-005
Intel 10 Gigabit CX4 Dual Port Server Adapter, (Cedar Cove Retail)	EXPX9502CX4	895897	E30197-005	E30197-006	E37623-005	E37623-006
Intel Ethernet Server Adapter X520-T2 (Iron Pond Retail)	E10G42BT	902900	E91920-004	E91920-005	E95990-003	E95990-004
Intel Ethernet Server Adapter X520-T2 (Iron Pond OEM generic 5-pak)	E10G42BTG1P5	902916	E91770-006	E91770-007	E95989-007	E95989-008

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
December 19, 2011	00	Originally Published PCN