



Product Change Notification

109423 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109423 - 01
Change Title: Intel® Server Systems SR1600UR, SR1625UR, SR2600UR, SR2625UR, PCN 109423-01, Product Design, Baseboard Update, Documentation and CD updates, Reason for Revision: Removing HSC FW Update
Date of Publication: July 20, 2009

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Aug 14, 2009
---	--------------

Description of Change to the Customer:

Reason for Revision: Removing Hot Swap Controller (HSC) Firmware update from this PCN. This change will be documented in a future PCN.

Change 1) The baseboard included in the system is being updated. Changes include the system software, resistor values, and voltage regulator (VR) heat sink thermal interface material (TIM). Details of each of the changes to the baseboard can be found in PCN #109370.

Change 2) Documentation included in the system is being updated.
- The Quick Start Guide and Attention Document for each system are being updated with the latest information.
- A new document is being added to the systems specifically to provide instructions for installing and removing the heatsinks that are provided with each system.

Change 3) The resource CD provided with the system is being updated with the latest documents, drivers and utilities. The Intel Deployment Assistant (IDA) remains at version 3.1.

Change 4) The System Management Software (SMS) CD is being updated to version 3.5.1.

This change is occurring concurrently with PCNs 109436, 109497 and 109445

Customer Impact of Change and Recommended Action:

Intel does not foresee any adverse customer impact to these changes. Intel recommends performing a standard level of evaluation as updated product and software becomes available.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
SR1600UR	900983	E43330-003	E22554-604	E43330-004	E22554-605
SR1600URHS	900985	E43329-003	E22554-604	E43329-004	E22554-605
SR1625UR	900986	E43328-004	E22554-604	E43328-005	E22554-605
SR1625URSAS	900987	E43327-004	E22554-604	E43327-005	E22554-605
SR1600URHSNA	901126	E43329-003	E22554-604	E43329-004	E22554-605
SR1600URNA	901125	E43330-003	E22554-604	E43330-004	E22554-605
SR1625URNA	901132	E43328-004	E22554-604	E43328-005	E22554-605
SR1625URSASNA	901136	E43327-004	E22554-604	E43327-005	E22554-605
SR2600URLX	900988	E43324-004	E22554-604	E43324-005	E22554-605
SR2625URBRP	900989	E43325-004	E22554-604	E43325-005	E22554-605
SR2625URLX	900990	E43326-004	E22554-604	E43326-005	E22554-605
SR2600URBRP	901093	E43323-004	E22554-604	E43323-005	E22554-605
SR2625URLXNA	901129	E43326-004	E22554-604	E43326-005	E22554-605
SR2600URLXNA	901131	E43324-004	E22554-604	E43324-005	E22554-605
SR2625URBRPNA	901141	E43325-004	E22554-604	E43325-005	E22554-605
SR2600URBRPNA	901187	E43323-004	E22554-604	E43323-005	E22554-605

Reference Documents / Attachments:

Document: _____ Location #: _____

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
July 10, 2009	00	Originally Published PCN
July 20, 2009	01	Removing HSC FW Update