



Product Change Notification

107721 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107721 - 00

**Change Title: D201GLY, PCN 107721-00,
Product Design, Fab Spin for
Quality Improvement**

Date of Publication: July 09, 2007

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Aug 30, 2007
---	--------------

Description of Change to the Customer:

Intel Desktop Board D201GLY will be changed to new fab for quality improvement

Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. CDPG is not recommending additional qualification of these changes on platforms received from Intel. These board changes are not expected to cause a change to the Microsoft* Windows* operating system's software driver stack. No expected OS image change.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change AA	Pre Change PBA	Post Change AA	Post Change PBA
LAD201GLYLT 887701	887701	D78099-305	D78100-305	D78099-400	D78100-400
LAD201GLYL 887702	887702	D76864-304	D81208-304	D76864-400	D81208-400
BLKD201GLYL 887958	887958	D81205-304	D81208-304	D81205-400	D81208-400
BOXD201GLYL 887961	887961	D81205-304	D81208-304	D81205-400	D81208-400

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

July 9, 2007

Revision Number:

00

Reason:

Originally Published PCN