



# Product Change Notification

## 109575 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** <mailto:asmo.pcn@intel.com>

**Asia Pacific Contact:** <mailto:apacgccb@intel.com>

**Europe Email:** <mailto:eccb@intel.com>

**Japan Email:** <mailto:jccb.ijkk@intel.com>

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 109575 - 00  
**Change Title:** DQ43AP, PCN 109575-00, Product Material, Added floppy drive connector and updated the BIOS  
**Date of Publication:** September 10, 2009

## Key Characteristics of the Change:

Product Material

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Sep 30, 2009
---	--------------

## Description of Change to the Customer:

Intel has implemented the following changes:  
Added a floppy drive connector on the board.  
Updated the BIOS to APQ4310H.86A.0028 to add floppy drive support.

To access release notes or a copy of the BIOS for evaluation, please go to <http://downloadcenter.intel.com>

## Customer Impact of Change and Recommended Action:

It is recommended that customers who created drive images with BIOS APQ4310H.86A.0027 installed evaluate the new boards to ensure a smooth transition as a driver install box may be seen if the new floppy controller is detected. For customers not affected by the above condition, Intel is not recommending additional qualification of these changes on desktop boards received from Intel.

## Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change AA	Post Change AA
BOXDQ43AP	901975	E60578-203	E60578-204
BLKDQ43AP	901976	E60578-203	E60578-204

## Reference Documents / Attachments:

**Document:** \_\_\_\_\_ **Location #:** \_\_\_\_\_

## PCN Revision History:

<b>Date of Revision:</b> September 10, 2009	<b>Revision Number:</b> 00	<b>Reason:</b> Originally Published PCN
--	-------------------------------	--