



Product Change Notification

110984 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2011. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 110984 - 00
Change Title: Intel(R) Server Board S5520HC, S5520HCT, S5500HCV and Intel(R) Workstation Board S5520SC, PCN 110984-00, Product Design, Change CPU socket protective cover
Date of Publication: September 20, 2011

Key Characteristics of the Change:


Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Oct 31, 2011
---	--------------

Description of Change to the Customer:

Intel will implement the following change on the Intel(R) Server Board S5520HC, S5520HCT, S5500HCV and Intel(R) Workstation Board S5520SC: Update the CPU protective cover to reduce the possibility of pin damage during processor installation. Below is a picture of the new protective plate cover:



Customer Impact of Change and Recommended Action:

The CPU socket protective cover change has no functional impact but may require a process change when inserting a CPU into the server board, so manufacturing documentation may need to be updated.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change Product Code	Post Change MM#	Post Change TA	Post Change PBA
S5520HCT	904912	E84149-555	E80888-555	S5520HCT	904912	E84149-556	E80888-556
BB5520HCR	905718	E87613-454	E26045-455	BB5520HCR	905718	E87613-455	E26045-456
BB5520SCR	905719	E87227-	E30682-	BB5520SCR	905719	E87227-	E30682-

		354	356			355	357
BB5500HCVR	905720	E88252-454	E40912-456	BB5500HCVR	905720	E88252-455	E40912-457
S5500HCVR	905723	E87505-455	E40912-456	S5500HCVR	905723	E87505-456	E40912-457
S5520HCR	905721	E87228-455	E26045-455	S5520HCR	905721	E87228-456	E26045-456
S5520SCR	905722	E87503-355	E30682-356	S5520SCR	905722	E87503-356	E30682-357

PCN Revision History:

Date of Revision:

September 20, 2011

Revision Number:

00

Reason:

Originally Published PCN