



# Product Change Notification

## 110874 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

Asia Pacific Contact: [apacgccb@intel.com](mailto:apacgccb@intel.com)

Europe Email: [eccb@intel.com](mailto:eccb@intel.com)

Japan Email: [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2011. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 110874 - 00  
**Change Title:** Intel(R) Server Chassis P4304XXSFCN,  
Intel(R) Server Chassis P4304XXSHCN,  
Intel(R) Server System P4304BTL SFCN,  
Intel(R) Server System P4304BTL SHCN,  
PCN 110874-00, Product Design, Product  
Design, Chassis design improvement  
**Date of Publication:** July 21, 2011

## Key Characteristics of the Change:


Product Design

## Forecasted Key Milestones:


<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Aug 26, 2011
---	--------------

## Description of Change to the Customer:

1. Intel will implement the following changes on the Intel(R) Server Chassis P4304XXSFCN and P4304XXSHCN, Intel(R) Server System P4304BTL SFCN and P4304BTL SHCN:
  - 1.1 Add a blue plastic cap to the Optical Disk Drive (ODD) rail user access point. The following are pictures of prior and post change:




- 1.2 Replace the chassis feet plastic pin with a plastic M4 screw, so the chassis feet can be removed by unfastening the screw with a screwdriver from outside of the chassis. The following are pictures of prior and post change product :



2. Intel will implement following change on Intel(R) Server Chassis P4304XXSFCN and Intel(R) Server System P4304BTL SFCN:

2.1 Add a lock clip to the fixed Hard Disk Drive (HDD) Electromagnetic Interference (EMI) shield to improve the lock mechanism. The following is a picture of the change:



**Customer Impact of Change and Recommended Action:**

No adverse customer impact is expected from these changes. Customers are expected to evaluate potential impact as updated product becomes available.

**Products Affected / Intel Ordering Codes:**

Product Code	Pre Change MM#	Pre Change TA	Post Change MM#	Post Change TA

P4304XXSFCN	911754	G15844-004	911754	G15844-005
P4304XXSFCNNA	907811	G15844-004	907811	G15844-005
P4304XXSHCN	911765	G21447-003	911765	G21447-004
P4304XXSHCNNA	907812	G21447-003	907812	G21447-004
P4304BTLSFCN	912776	G22757-002	912776	G22757-003
P4304BTLSFCNNA	908252	G22757-002	908252	G22757-003
P4304BTLSHCN	912775	G22759-002	912775	G22759-003
P4304BTLSHCNNA	907886	G22759-002	907886	G22759-003

### **PCN Revision History:**

**Date of Revision:**

July 21, 2011

**Revision Number:**

00

**Reason:**

Originally Published PCN