



Product Change Notification

112868 - 01

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jcb.ijkk@intel.com

Copyright © Intel Corporation 2014. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 112868 – 01
Change Title: Shipping Media Empty Pocket Quantity Change for Select Chipset Products
PCN112868-01, Transport Media
Reason for Revision: Empty Pocket Quantity Change Update

Date of Publication: September 23, 2014

Key Characteristics of the Change:

Transport Media

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	May 26, 2014
---	--------------

Description of Change to the Customer:

Reason for Revision: New Empty Pocket Quantity Change Update

The values listed in the PCN published on April 23, 2014 have changed. The new values are reflected in the **Revised Leader/Trailer Matrix** below. No other changes have been made to the PCN or products in the Products Affected/Intel Ordering Codes table.

Revised Leader/Trailer Matrix


Product	Current Leader Value	Current Trailer Value	Current Total	New Leader Value	New Trailer Value	New Total
Intel® 8 Series Chipsets - Desktop	45	45	90	40	24	64
Intel® 8 Series Chipsets - Mobile	45	45	90	40	28	68
All other products listed on the Products Affected/Intel Ordering Codes table	30	30	60	30	21	51

Intel is decreasing the number of empty pockets on the leader/trailer tape for select chipset products packed in tape and reel to reduce unnecessary packing material. Please see the current and new leader/trailer values in the matrix above. This change will not affect the integrity of the reel or reduce the protection of the units. Please refer to the diagram provided under the Customer Impact of Change and Recommended Action section of the PCN.

Product	Current Leader Value	Current Trailer Value	Current Total	New Leader Value	New Trailer Value	New Total
Intel® 8 Series Chipsets - Desktop	45	45	90	40	22	62
Intel® 8 Series Chipsets - Mobile	45	45	90	40	16	56
All other products listed on the Products Affected/Intel Ordering Codes table	30	30	60	30	20	50

Customer Impact of Change and Recommended Action:

Intel does not anticipate any impact to our customers. Customers may see both shipments of reels packed with either the current leader/trailer quantities or reels with the new reduced leader/trailer quantities until all inventory has been depleted. Diagram showing the side view of the reel:



Products Affected/Intel Ordering Codes:

Intel® 8 Series Chipset products are noted in blue.

Marketing Name	Platform	Stepping	Product Code	S-Spec	MM#
Intel® BD82QM57 Platform Controller Hub	Mobile	B3	BD82QM57	S LGZQ	904125
Intel® BD82HM55 Platform Controller Hub	Mobile	B3	BD82HM55	S LGZS	904127
Intel® BD82Q57 Platform Controller Hub	Desktop	B3	BD82Q57	S LGZW	904131
Intel® BD3450 Platform Controller Hub	Server	B3	BD3450	S LGZY	904133
Intel® BD3420 Platform Controller Hub	Server	B3	BD3420	S LH25	904143
Intel® BD82H67 Platform Controller Hub	Desktop	B3	BD82H67	S LJ49	914378
Intel® BD82B65 Platform Controller Hub	Desktop	B3	BD82B65	S LJ4A	914379
Intel® BD82H61 Platform Controller Hub	Desktop	B3	BD82H61	S LJ4B	914380
Intel® BD82Q67 Platform Controller Hub	Desktop	B3	BD82Q67	S LJ4D	914397
Intel® BD82Q65 Platform Controller Hub	Desktop	B3	BD82Q65	S LJ4E	914407
Intel® BD82Z68 Platform Controller Hub	Desktop	B3	BD82Z68	S LJ4F	914416
Intel® BD82C206 Platform Controller Hub	Server	B3	BD82C206	S LJ4G	914417
Intel® BD82C204 Platform Controller Hub	Server	B3	BD82C204	S LJ4H	914418
Intel® BD82C202 Platform Controller Hub	Server	B3	BD82C202	S LJ4J	914419
Intel® BD82Q77 Platform Controller Hub	Desktop	C1	BD82Q77	S LJ83	915673
Intel® BD82Q75 Platform Controller Hub	Desktop	C1	BD82Q75	S LJ84	915674
Intel® BD82B75 Platform Controller Hub	Desktop	C1	BD82B75	S LJ85	915675
Intel® BD82Z75 Platform Controller Hub	Desktop	C1	BD82Z75	S LJ87	915677
Intel® BD82H77 Platform Controller Hub	Desktop	C1	BD82H77	S LJ88	915678
Intel® BD82Z77 Platform Controller Hub	Desktop	C1	BD82Z77	S LJC7	918608
Intel® BD82C216 Platform Controller Hub	Server	C1	BD82C216	S LJ8H	915680
Intel® DH82Q87 Platform Controller Hub	Desktop	C2	DH82Q87	S R173	929132
Intel® DH82Q85 Platform Controller Hub	Desktop	C2	DH82Q85	S R174	929133

Marketing Name	Platform	Stepping	Product Code	S-Spec	MM#
Intel® DH82H87 Platform Controller Hub	Desktop	C2	DH82H87	S R175	929134
Intel® DH82Z87 Platform Controller Hub	Desktop	C2	DH82Z87	S R176	929136
Intel® DH82H81 Platform Controller Hub	Desktop	C2	DH82H81	S R177	929137
Intel® DH82B85 Platform Controller Hub	Desktop	C2	DH82B85	S R178	929138
Intel® DH82QM87 Platform Controller Hub	Mobile	C2	DH82QM87	S R17C	929149
Intel® DH82HM87 Platform Controller Hub	Mobile	C2	DH82HM87	S R17D	929151
Intel® DH82HM86 Platform Controller Hub	Mobile	C2	DH82HM86	S R17E	929152
Intel® DH82C224 Platform Controller Hub	Server	C2	DH82C224	S R17A	929142
Intel® DH82C222 Platform Controller Hub	Server	C2	DH82C222	S R17B	929144
Intel® DH82C226 Platform Controller Hub	Workstation Server	C2	DH82C226	S R179	929139
Intel® BD82C608 Platform Controller Hub	Server	C1	BD82C608	S LJKF	919597
Intel® BD82C602 Platform Controller Hub	Server	C1	BD82C602	S LJKG	919598
Intel® BD82C606 Platform Controller Hub	Server	C1	BD82C606	S LJKH	919599
Intel® BD82C604 Platform Controller Hub	Server	C1	BD82C604	S LJKJ	919601
Intel® BD82X79 Platform Controller Hub	Server	C1	BD82X79	S LJN7	920099
Intel® BD82C602J Platform Controller Hub	Server	C1	BD82C602J	S LJNG	920240

PCN Revision History:

Date of Revision:

April 23, 2014
September 23, 2014

Revision Number:

00
01

Reason:

Originally Published PCN
Empty Pocket Quantity Change
Update