



Product Change Notification

#112267- 00

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia/PRC Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2013. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 112267-00
Change Title: Intel® Core™ i3, i5 & i7 Series Processors & Intel® Pentium® 3550M, 3560M & 3570M Processors & Intel® Celeron® 2950M, 2960M, 2970M, & 2980M Processors, PCN 112267-00, Label, Country of Origin Label Adding China
Date of Publication: June 20, 2013

Key Characteristics of the Change:
 Label


Forecasted Key Milestones:

	Date
Date Customer Must be Ready to Receive Post-Conversion Material:	July 20, 2013

Description of Change to the Customer:

In order to ensure a continuous supply of the Intel® Core™ i3, i5 & i7 Series Processors & Intel® Pentium® 3550M, 3560M & 3570M Processors & Intel® Celeron® 2950M, 2960M, 2970M, & 2980M Processors, listed in the "Products Affected" Table below, Intel will now manufacture these products using another Intel qualified assembly site. The new site is located in China. The new manufacturing site has been certified equivalent (form, fit, function, and reliability) for the affected products and technologies of this change.

Due to this change, the "ASSEMBLED IN (Country)" on the Intermediate Box Label, see example below, will now include China. All material and equipment will remain the same.



Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers for this change. Customers may see products from all assembly sites. Customers may want to notify their receiving department of the additional Country of Origin marking.

Products Affected / Intel Ordering Codes:

Marketing Name	Processor#	Frequency	Stepping	Product Code	S-Spec	MM#
Intel® Core Processor	i7-4700MQ	2.4 GHz	C0	CW8064701470702	S R15H	928035
Intel® Core Processor	i7-4702MQ	2.2 GHz	C0	CW8064701470802	S R15J	928036
Intel® Core Processor	i7-4900MQ	2.8 GHz	C0	CW8064701470901	S R15K	928037
Intel® Core Processor	i7-4800MQ	2.7 GHz	C0	CW8064701471001	S R15L	928038
Intel® Core Processor Extreme	i7-4930MX	3.0 GHz	C0	CW8064701471101	S R15M	928039
Intel® Core Processor	i3-4000M	2.4 GHz	C0	CW8064701484702	S R15Q	928042
Intel® Core Processor	i7-4600M	2.9 GHz	C0	CW8064701486306	S R1H7	930777
Intel® Core Processor	i5-4330M	2.8 GHz	C0	CW8064701486406	S R1H8	930778
Intel® Core Processor	i5-4300M	2.6 GHz	C0	CW8064701486506	S R1H9	930779
Intel® Core Processor	i5-4200M	2.5 GHz	C0	CW8064701486606	S R1HA	930780
Intel® Core Processor	i3-4100M	2.5 GHz	C0	CW8064701486707	S R1HB	930781
Intel® Core Processor	i3-4000M	2.4 GHz	C0	CW8064701486802	S R1HC	930782
Intel® Pentium® Processor	3550M	2.3 GHz	C0	CW8064701486907	S R1HD	930783
Intel® Pentium® Processor	3550M	2.4 GHz	C0	CW8064701486906	S R1HE	930784
Intel® Celeron® Processor	2950M	2.0 GHz	C0	CW8064701487007	S R1HF	930785
Intel® Core Processor	i7-4610M	3.0 GHz	C0	CW8064701486301	S R1KY	931056
Intel® Core Processor	i7-4620M	3.1 GHz	C0	CW8064701486303	S R1KZ	931057
Intel® Core Processor	i5-4340M	2.9 GHz	C0	CW8064701486401	S R1L0	931058
Intel® Core Processor	i5-4350M	3.0 GHz	C0	CW8064701486402	S R1L1	931059
Intel® Core Processor	i5-4310M	2.7 GHz	C0	CW8064701486501	S R1L2	931060
Intel® Core Processor	i5-4320M	2.8 GHz	C0	CW8064701486502	S R1L3	931061
Intel® Core Processor	i5-4210M	2.6 GHz	C0	CW8064701486601	S R1L4	931062
Intel® Core Processor	i5-4220M	2.7 GHz	C0	CW8064701486602	S R1L5	931063
Intel® Core Processor	i5-4230M	2.8 GHz	C0	CW8064701486603	S R1L6	931064
Intel® Core Processor	i3-4110M	2.6 GHz	C0	CW8064701486708	S R1L7	931065
Intel® Core Processor	i3-4120M	2.7 GHz	C0	CW8064701486709	S R1L8	931068
Intel® Core Processor	i3-4130M	2.8 GHz	C0	CW8064701486710	S R1L9	931072
Intel® Core Processor	i3-4010M	2.5 GHz	C0	CW8064701486806	S R1LA	931073
Intel® Core Processor	i3-4020M	2.6 GHz	C0	CW8064701486807	S R1LB	931076
Intel® Pentium® Processor	3560M	2.4 GHz	C0	CW8064701486906	S R1LC	931077
Intel® Pentium® Processor	3570M	2.5 GHz	C0	CW8064701486901	S R1LD	931078
Intel® Celeron® Processor	2960M	2.1 GHz	C0	CW8064701487006	S R1LE	931079
Intel® Celeron® Processor	2970M	2.2 GHz	C0	CW8064701487001	S R1LF	931080
Intel® Celeron® Processor	2980M	2.3 GHz	C0	CW8064701487002	S R1LG	931081

PCN Revision History:

Date of Revision:

June 20, 2013

Revision Number:

00

Reason:

Originally Published PCN