



Product Change Notification

Change Notification #: 114478 - 01
Change Title: Intel® NUC Kit, NUC6i5SYH and Intel® NUC Kit, NUC6i5SYK, PCN 114478-01, Product Design, Product Material, BIOS Update and Component Change, Reason for Revision: BIOS version change and milestone update
Date of Publication: April 11, 2016

Key Characteristics of the Change:
Product Design, Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Apr 18, 2016
---	---------------------

Description of Change to the Customer:

Reason for Revision: BIOS version change and milestone update

The Intel® NUC Kit, NUC6i5SYH and Intel® NUC Kit, NUC6i5SYK SKUs listed in the products affected table below will have the following changes.

1. The BIOS will be updated from SY0028 to **SY0042**. To access the release notes or get a copy of the BIOS for evaluation, go to <http://downloadcenter.intel.com>.
2. The capacitors at locations SC181, SC190, and SC282 will be changed from 22uF to 47uF to improve memory compatibility.

Customer Impact of Change and Recommended Action:

It is recommended that customers evaluate this new BIOS to ensure a smooth transition. These change has been thoroughly evaluated to ensure that there are no quality or reliability implications to our customers. Intel validation of a new board revision does not include testing with older versions of BIOS. This change is not expected to cause a change to the Microsoft Windows* operating system's software driver stack.

Intel will attempt to deplete pre-conversion material before shipping post-conversion material but there is a possibility of Intel shipping mixed inventory. Therefore, customers will need to manage and migrate to the post-conversion material as soon as possible.

Milestone dates are estimates and subject to change based on business and operational conditions. Please contact your local Intel Field Sales Rep if you have any further questions about these changes.

Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change SA	Pre Change AA	Post Change SA	Post Change AA
BOXNUC6I5SYK	943204	H87089-502	H81131-502	H87089-503	H81131-503
BOXNUC6I5SYH	943207	H87090-502	H81131-502	H87090-503	H81131-503
BOXNUC6I5SYKL	946869	H95046-502	H81131-502	H95046-503	H81131-503
BOXNUC6I5SYHL	946874	H95047-502	H81131-502	H95047-503	H81131-503

PCN Revision History:

Date of Revision:

March 18, 2016

April 11, 2016

Revision Number:

00

01

Reason:

Originally Published PCN

BIOS version change and
milestone update



Product Change Notification

114478 - 01

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2016. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.

