



Product Change Notification

109780 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: <mailto:asmo.pcn@intel.com>

Asia Pacific Contact: <mailto:apacgccb@intel.com>

Europe Email: <mailto:eccb@intel.com>

Japan Email: <mailto:jccb.ijk@intel.com>

Copyright © Intel Corporation 2010. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109780 - 00
Change Title: DG41MJ, PCN 109780-00, Product Material, Update BIOS and add alternate part for SPI flash memory
Date of Publication: January 07, 2010

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jan 30, 2010
---	--------------

Description of Change to the Customer:

Intel has implemented the following changes:

1. BIOS update from MJG4110H.86A.0003 to MJG4110H.86A.0006. To access release notes or a copy of the Bios for evaluation, go to <http://downloadcenter.intel.com>.
2. Add alternate part for SPI flash memory.

Customer Impact of Change and Recommended Action:

It is recommended that customers evaluate this new BIOS to ensure a smooth transition. This change has been thoroughly evaluated to ensure that there are no quality or reliability implications to our customers. Intel is not recommending additional qualification; however, the updated boards may not be able to be use recovery or Intel® Iflash to previous BIOS versions. This change is not expected to cause a change to the Microsoft Windows* operating system's software driver stack.

Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change AA	Post Change AA
BOXDG41MJ	900996	E54659-204	E54659-205
BLKDG41MJ	900997	E54659-204	E54659-205
LADG41MJ	901000	E54660-203	E54660-204

PCN Revision History:

Date of Revision: January 7, 2010	Revision Number: 00	Reason: Originally Published PCN
---	-------------------------------	--