



Product Change Notification

Change Notification #: 119240-01

Change Title: Select Intel® Server Chassis, Spares and Accessories
PCN 119240-01, Product Discontinuance,
Reason for Revision: MMID 960190 is no longer available for orders due to depleted inventory

Date of Publication: November 23, 2022

Key Characteristics of the Change:

Product Discontinuance

Forecasted Key Milestones:

Product Discontinuance Program Support Begins*	August 26, 2022
Last Product Discontinuance Order Date*	December 30, 2022
Orders are Non-Cancelable and Non-Returnable After**	September 30, 2022
Last Product Discontinuance Shipment Date*	June 30, 2023

Description of Change to the Customer:

Reason for Revision: This revision is to inform customers that MMID 960190 is no longer available for orders as of November 23, 2022, due to depleted inventory.

Intel is announcing the discontinuance of the Intel® Server Chassis, Spares and Accessories listed in the "Products Affected/Intel Ordering Codes" table below.

Intel will make best efforts to support all orders placed between the Non-Cancelable and Non-Returnable (NCNR) and the Last Product Discontinuance Order (LPDO) dates. Intel will discontinue builds on the LPDO date. After the LPDO date existing inventory is still orderable, under NCNR terms, and will be filled on a first come first served basis. Deliveries must be accepted within 90 days from the LPDO date.

Final purchase orders are non-cancelable and non-returnable, notwithstanding any conflicting terms in our quotes, purchase order acknowledgement or Distributor agreements.

Intel reserves the right to change the products because of material source restriction.

Engineering and Support Guidance for Discontinued Products:

1. No new OS, peripheral or adaptor validation is planned during the extended life period. The THOL, supported processor and tested memory lists are frozen at PDA.
2. No new features enhancements should be expected, however ECOs may be required during the extended life period to maintain supply lines (e.g., to qualify new vendor due to a component EOL).

Intel will provide reasonable commercial efforts in debugging issues during the warranty period for the product after the PDA date has passed. Fixes cannot be committed, but Intel will endeavor to provide reasonable workarounds for the product.

Customer Impact of Change and Recommended Action:

Determine your remaining demand for this product and/or evaluate additional sources (if applicable). Lead-times on products with announced product discontinuance can typically stretch to 12 weeks and volumes are not buffered during the PDA period. Please work with your Intel representative on your quarterly demand forecast in order to reduce lead-times to 2-4 Weeks. Please contact your local Intel Sales Office or Distributor if you require more information or need assistance in selecting a replacement product. Milestone dates are estimates and subject to change based on business and operational conditions. .

Products Affected/Intel Ordering Codes:

Marketing Name	Product Code	Affected MM#
Non-Redundant Power Supply Adapter Bracket FUPNRPSADP, Single	FUPNRPSADP	912769
Spare 3.5in Fixed HDD Carriers FUP4X35NHDK, Single	FUP4X35NHDK	912770
Redundant Power Supply Cage FUPCRPSCAGE (for Intel® Server Chassis P4000 Family), Single	FUPCRPSCAGE	915607
Spare Hot-Swap Fan Kit FUPMLHSFAN (For Intel® Server Chassis P4000M and P4000L), Single	FUPMLHSFAN	915620
Rack Bezel Frame (No Door) AUPBEZEL4UF(for Intel® Server Chassis P4000 Family), Single	AUPBEZEL4UF	915636
Rack Bezel Door AUPBEZEL4UD (for Intel® Server Chassis P4000 Family), Single	AUPBEZEL4UD	915637
Chassis Mechanical Maintenance Kit FUPMMSK (for Intel® Server Chassis P4000M), Single	FUPMMSK	915638
Bezel Spare FUPBEZELFIX2 for P4000 Chassis Supporting Fixed HDD, Single	FUPBEZELFIX2	925750
Accessory Airduct A4UCWDUCT, Single	A4UCWDUCT	936419
Power Adapter FXXSSIPWR, OEM 10 pack	FXXSSIPWR	936430
Intel® Server Chassis P4304XXMUXX, Single	P4304XXMUXX	937011
Spare RoHS Compliant Front Panel FXXFPANELR, Single	FXXFPANELR	946534
8x2.5 inch Dual Port SAS Hot Swap Drive Bay Kit AUP8X25S3DPDK, Single	AUP8X25S3DPDK	953392
8x2.5 inch Hot Swap SAS/NVMe COMBO Drive Bay Kit AUP8X25S3NVDK, Single	AUP8X25S3NVDK	953393
Front Panel Cable Kit AXXSTFPCBLKIT, Single	AXXSTFPCBLKIT	959730
3.5 inch Hot-swap Drive Bay Kit AUP4X35S3HSDK, Single	AUP4X35S3HSDK	959879
GPGPU Bracket Kit AXXSTPHIKIT, Single	AXXSTPHIKIT	959897
I2C Cable Kit AXXSTI2CCBL, Single	AXXSTI2CCBL	960398
Spare SATA Power Adapter Cable AXXSTCBLSATA, Single	AXXSTCBLSATA	960399
Spare Redundant FAN Cable Kit FXXSTCBLFAN, Single	AXXSTCBLFAN	960404
95mm QAT Bridge Cable AXXSTCBLQAT, Single	AXXSTCBLQAT	959878
Lan Riser Cable Kit AXXSTSFPFKIT, Single	AXXSTSFPFKIT	960190
BBU Bracket Kit AXXSTBBUBRKT, Single	AXXSTBBUBRKT	959895

PCN Revision History:

Date of Revision: **Revision Number:** **Reason:**

August 26, 2022 00

Originally Published PCN

November 23, 2022 01

MMID 960190 is no longer available for orders
due to depleted inventory



Product Change Notification

119240-01

Notices & Disclaimers

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade, except as provided in a separate written agreement.

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes the subject matter disclosed herein.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Statements in this document that refer to future plans or expectations are forward-looking statements. These statements are based on current expectations and involve many risks and uncertainties that could cause actual results to differ materially from those expressed or implied in such statements. For more information on the factors that could cause actual results to differ materially, see our most recent earnings release and SEC filings at www.intc.com.

Customer is responsible for safety of the overall system, including compliance with applicable safety-related requirements or standards.

Intel technologies may require enabled hardware, software or service activation.

No product or component can be absolutely secure.

Your costs and results may vary.

©Intel Corporation. Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries. Other names and brands may be claimed as the property of others.

No response from customers will be deemed an acceptance of the change, and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com
Japan Email: jcb.ijkk@intel.com