



Product Change Notification

111976 - 00

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2012. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 111976 - 00
Change Title: Intel® Server Board S2600CP Product Family
PCN 111976-00, Product Design, Transport Media
Update Transport Media and BIOS/BMC/FRUSDR
Date of Publication: December 19, 2012

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jan 11, 2013
---	--------------


Description of Change to the Customer:

The following changes are being made to the Intel® Server Board S2600CP Family OEM 10-pack package material:


1. Make the paper strip 30mm wider to increase packaging strength to protect the video connector and improve support for the server board. The following is a picture that shows where this strip goes in the package box:



The following are pictures of the pre and post change of the strip:



2. Add more holes to the packaging and change the folding solution on the side partition to improve support for the server board. The following are pictures of the pre and post change:



Intel will implement the following firmware changes on Intel® Server Board S2600CP Family Products listed on the Products Affected / Intel Ordering Codes table below.

1. Update the BIOS from revision 01.03.0002 to 01.06.0001
2. Update the Integrated Baseboard Management Controller (BMC) firmware from revision 0110 r3560 to 0116 r4010
3. Update the FRUSDR from revision 1.07 to 1.08

Customer Impact of Change and Recommended Action:

Intel recommends that the customer perform a standard level of evaluation. Customers can download the latest firmware package from <http://www.intel.com/support>.

Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
BBS2600CP2	916039	G41268-503	G50768-508	G41268-504	G50768-509
DBS2600CP2	916040	G41269-503	G50768-508	G41269-504	G50768-509
DBS2600CP4	916041	G41273-503	E99552-508	G41273-504	E99552-509
BBS2600CP4	916042	G41271-503	E99552-508	G41271-504	E99552-509
DBS2600CP2IOC	920971	G56225-503	G50768-508	G56225-504	G50768-509
DBS2600CP4IOC	920972	G56226-503	E99552-508	G56226-504	E99552-509
BBS2600CP2J	921042	G56510-503	G56797-508	G56510-504	G56797-509

PCN Revision History:

Date of Revision:
December 19, 2012

Revision Number:
00

Reason:
Originally Published PCN