



Product Change Notification

113613 - 00

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2015. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 113613 - 00
Change Title: Intel® Spare Bridge Board for HNS2400LP
Computing Module Family FHWLPBGB
PCN 113613-00, Product Discontinuance
End of Life
Date of Publication: January 30, 2015

Key Characteristics of the Change:

Product Discontinuance

Forecasted Key Milestones:

Last Product Discontinuance Order Date *:	Mar. 31, 2015
Last Product Discontinuance Shipment Date:	Jun. 30, 2015

** Intel appreciates the customer's desire to receive the latest revision of products. However, Intel manages inventory on a first in first out (FIFO) basis at the MM# level. Subsequently, customer requests for a specific revision of material (below the MM#) will not be supported by Intel.*

Description of Change to the Customer:

Intel is announcing the discontinuance of Intel® Spare Bridge Board for HNS2400LP Computing Module Family FHWLPBGB listed in the "Products Affected/Intel Ordering Codes" table below.

Date (example)	Definition
Jan. 30, 2015	PDA: Product Discontinuance Announced.
	Business as usual. Distributor stock rotation returns will be accepted up until the NCNR date.
Feb. 15, 2015	NCNR: Non-Cancelable and Non-Returnable date.
	Intel will make best efforts to support all orders placed between NCNR and FCFS. Deliveries must be accepted within 90 days from the FCFS date.
Feb. 15, 2015	FCFS: First Come First Served Order Date
	Existing inventory is still orderable, under NCNR terms, and will be filled on a first come first served basis. Intel will discontinue product builds on the FCFS date. Deliveries must be accepted within 90 days.

Final purchase orders are non-cancelable and non-returnable, notwithstanding any conflicting terms in our quotes, purchase order acknowledgment, or Distributor agreements.

Intel reserves the right to change the products because of material source restriction.

Customer Impact of Change and Recommended Action:

Please determine your remaining demand for this product and/or evaluate additional sources (if applicable).

Please contact your local Intel Sales Office or Distributor if you require more information or need assistance in selecting a replacement product.

Milestone dates are estimates and subject to change based on business and operational conditions.

Products Affected / Intel Ordering Codes:

Product Name	Product Code	Pre Change Affected MM#	Recommended Replacement Product Code	Recommended Replacement MM#
Intel® Spare Bridge Board for HNS2400LP Computing Module Family	FHWLPBGB	920834	NA	NA

PCN Revision History:

Date of Revision:

January 30, 2015

Revision Number:

00

Reason:

Originally Published PCN