



Product Change Notification

PCN113429-00

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia/PRC Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2014. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: PCN113429-00
Change Title: Intel® Xeon® Processors and Intel® Celeron® Processor PCN113429-00, Label, Country of Origin addition
Date of Publication: November 18, 2014

Key Characteristics of the Change:

Label

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Dec 19, 2014
---	--------------

Description of Change to the Customer:

In order to ensure a continuous supply of the Intel® Xeon® Processors listed in the "Products Affected" Table below, Intel will be transferring these products to another Intel qualified assembly site. The new site is located in Malaysia. The new manufacturing site has been certified equivalent (form, fit, function, and reliability) for the affected products and technologies of this change.

Due to this change, the "ASSEMBLED IN Country" on the box label will now include Malaysia. See label example below – This label is a representation for example purposes only. The actual label will reflect correct product data.



If the Country of Origin (COO) identification is marked on the product, this will now display MALAY.

Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers for this change. Customers may receive product from either site until existing inventory is depleted. Customers may want to notify their receiving department of the new Country listed on the label.

Products Affected / Intel Ordering Codes:

Marketing Name	Processor#	Frequency	Stepping	Product Code	S-Spec	MM#
Intel® Xeon® Processor	E5540	2.53 GHZ	D0	AT80602000789AA	S LBF6	900838
Intel® Xeon® Processor	E5520	2.26 GHZ	D0	AT80602002091AA	S Lbfd	900840
Intel® Xeon® Processor	E5504	2.0 GHZ	D0	AT80602000801AA	S LBF9	900842
Intel® Xeon® Processor	W3505	2.53 GHZ	D0	AT80601002865AA	S LBGC	901494
Intel® Xeon® Processor	L5518	2.13 GHZ	D0	AT80602002265AB	S LBFW	901505
Intel® Xeon® Processor	L5508	2.0 GHZ	D0	AT80602002697AC	S LBGK	901549
Intel® Xeon® Processor	EC5549	2.53 GHZ	B0	AT80612005712AB	S LBWP	907831
Intel® Xeon® Processor	LC5518	1.73 GHZ	B0	AT80612002928AC	S LBWF	907832
Intel® Xeon® Processor	LC3528	1.73 GHZ	B0	AT80612002931AB	S LBWG	907833
Intel® Xeon® Processor	LC3518	1.73 GHZ	B0	AT80612002946AA	S LBWH	907834
Intel® Xeon® Processor	EC5539	2.27 GHZ	B0	AT80612003861AB	S LBWL	907835
Intel® Celeron® Processor	P1053	1.33 GHZ	B0	AT80612004743AA	S LBWN	907836
Intel® Xeon® Processor	EC5509	2.0 GHZ	B0	AT80612004740AA	S LBWM	907837
Intel® Xeon® Processor	EC3539	2.13 GHZ	B0	AT80612003090AA	S LBWJ	907838
Intel® Xeon® Processor	LC5528	2.13 GHZ	B0	AT80612003858AA	S LBWK	907839

PCN Revision History:**Date of Revision:**

November 18, 2014

Revision Number:

00

Reason:

Originally Published PCN