



Product Change Notification

108738 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 108738 - 00
Change Title: S3210SHLC; S3200SHV; S3210SHLX, PCN 108738-00, Product Material, Update Intel® System Management Software from 2.0 to 3.0; remove 2 SATA cables
Date of Publication: August 18, 2008

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Sep 13, 2008
---	--------------

Description of Change to the Customer:

Updating Intel® System Management Software from 2.0 to 3.0; removing 2 SATA cables from boxed boards.

Customer Impact of Change and Recommended Action:

Intel(R) System Management Software 3.0 is DVD version. Customers will need DVD-ROM to install version 3.0.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Post Change MM#	Post Change TA
S3200SHV 897886	897886	E12678-301	897886	E12678-302
S3210SHLC 897888	897888	E12677-301	897888	E12677-302
S3210SHLX 897890	897890	E12673-301	897890	E12673-302

Reference Documents / Attachments:

Document: _____ **Location #:** _____

PCN Revision History:

Date of Revision: August 18, 2008	Revision Number: 00	Reason: Originally Published PCN
---	-------------------------------	--