



# Product Change Notification

## 111373 - 01

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

Asia Pacific/PRC Contact: [apacgccb@intel.com](mailto:apacgccb@intel.com)

Europe Email: [eccb@intel.com](mailto:eccb@intel.com)

Japan Email: [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2012. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 111373 - 01

**Change Title:** Intel® I/O Controller Hubs, PCN 111373-01, Documentation, Carrier Tape Change for Tape and Reel Packed Products, Reason for Revision: MM# 898134, AM82801IUX S LB8N, should not have been included.

**Date of Publication:** March 26, 2012

## Key Characteristics of the Change:

Documentation

## Forecasted Key Milestones:


<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Apr 10, 2012
---	--------------

## Description of Change to the Customer:

**Reason for Revision: MM# 898134, AM82801IUX S LB8N, should not have been included.**

Intel will be replacing our current supplier of carrier tapes for tape and reel packed products. The new carrier tape design has full peripheral ledge supports as well as smaller pocket corner relief openings. All Critical-to-Function dimensions are the same. Since both the old and new carrier tapes have the same form factor, they are allowed to be mixed in a shipment as they are transparent in terms of functionality.

The 22x22mm package and the 31x31mm package carrier tapes will be changing from partial ledge supports to full ledge supports and smaller corner relieves with this carrier tape supplier change.



## Customer Impact of Change and Recommended Action:

The customer may receive tape and reel packed products that use carrier tape from either supplier until current inventories have been depleted. This will have no impact on the customer's manufacturing process.

## Products Affected / Intel Ordering Codes:

Product Code	S-Spec	MM#
FW82801CA S L632	S L632	843132
FW82801DBM S L6DN	S L6DN	848109
FW82801DB S L6DM	S L6DM	848140
NH82801CAM S L7A7	S L7A7	857393
FW82801FB S L7AG	S L7AG	857492
NH82801DBM S L7VK	S L7VK	864814
FW82801FB S L7Y5	S L7Y5	865377
NH82801EB S L7YC	S L7YC	865579
NH82801FBM S L89K	S L89K	868158
NH82801FB S L89L	S L89L	868390
NH82801CA S L8AN	S L8AN	868447
NH82801DB S L8DE	S L8DE	869490
NH82801GR S L8FY	S L8FY	870293
NH82801GB S L8FX	S L8FX	870379
NH82801E S L8LG	S L8LG	871695
FW82801GB S L8TF	S L8TF	874363
NH82801GDH S L8UK	S L8UK	874846
NH82801GBM S L8YB	S L8YB	876595
NH82801GHM S L8YR	S L8YR	876784
NH82801HR S L9MK	S L9MK	883292
NH82801HO S L9MM	S L9MM	883305
NH82801HB S L9MN	S L9MN	883306
PC82801GUX S L9U9	S L9U9	885312
NH82801IH S LA9P	S LA9P	890309
NH82801IB S LA9M	S LA9M	890310
NH82801IR S LA9N	S LA9N	890311
NH82801IO S LAFD	S LAFD	891192
FW82801IR S LAXE	S LAXE	896472
AF82801JIB S LB8R	S LB8R	898158
AF82801JIR S LB8S	S LB8S	898159
NH82801HBM S LB9A	S LB9A	898274
NH82801HEM S LB9B	S LB9B	898282
AF82801IBM S LB8Q	S LB8Q	898395
AF82801IEM S LB8P	S LB8P	898396
NH82801FPM S LG8L	S LG8L	898752
AF82801JD S LG8T	S LG8T	898942
AF82801JDO S LG8U	S LG8U	898943
DW82801HBM S LJ4Y	S LJ4Y	915071
DW82801HEM S LJ4Z	S LJ4Z	915072
DW82801HR S LJA9	S LJA9	917577
DW82801HO S LJAA	S LJAA	917578
DW82801HB S LJEW	S LJEW	917657
DW82801FBM S LJGN	S LJGN	918234
DW82801FB S LJGP	S LJGP	918235

EF82801FB S LJH3	S LJH3	918329
AF82US15W S LGFQ	S LGFQ	899760

### **PCN Revision History:**

**Date of Revision:**

March 9, 2012

March 26, 2012

**Revision Number:**

00

01

**Reason:**

Originally Published PCN

MM# 898134, AM82801IUX S  
LB8N, should not have been  
included.