



Product Change Notification

109437 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109437 - 00
Change Title: S5520HC, S5500HCV, S5520SC, PCN
109437-00, Product Material, Boxed Board
Resource CD, Intel® Server Management
Software DVD, and Documentation Update
Date of Publication: June 25, 2009

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jul 27, 2009
---	--------------

Description of Change to the Customer:

S5520HC:

- Attention Doc – update from E39543-006 to E39543-007
 - Update boxed board content list
- Remove software update procedure Attention Doc (E63695-001)
- Quick Start User's Guide – update from E39528-003 to E39528-005:
 - Update memory installation guide; Remove chassis intrusion cabling requirement when integrating into Intel Server Chassis; Update bumpers installation guide
 - The Quick Start User's Guide (E39528-005) is also available for download from Intel's support web site: <http://support.intel.com/support/motherboards/server/s5520HC/>
- Resource CD - update from E39464-003 to E30464-004:
 - Intel® Deployment Assistant update from v3.0 to v3.1; Driver and utility update
 - The resource CD image (Intel® Deployment Assistant ISO image) is available for download from Intel's support web site: <http://support.intel.com/support/motherboards/server/s5520HC/>
- Intel® Server Management Software (ISMS) DVD - update from v3.1 to v3.5

S5500HCV:

- Attention Doc – update from E39543-006 to E39543-007:
 - Update boxed board content list
- Remove software update procedure Attention Doc (E63695-001)
- Quick Start User's Guide – update from E39528-003 to E39528-005:
 - Update memory installation guide; Remove chassis intrusion cabling requirement when integrating into Intel Server Chassis; Update bumpers installation guide
 - The Quick Start User's Guide (E39528-005) is also available for download from Intel's support web site: <http://support.intel.com/support/motherboards/server/s5520HC/>
- Intel® Server Management Software (ISMS) DVD - update from 3.1 to 3.5

S5520SC:

- Attention Doc – update from E39544-003 to E39544-004:
 - Update boxed board content list
- Remove software update procedure Attention Doc (E63695-001)
- Quick Start User's Guide – update from E39546-003 to E39546-005:
 - Update memory installation guide; Remove chassis intrusion cabling requirement when integrating into Intel Server Chassis; Update bumpers installation guide; Update graphics card installation guide
 - The Quick Start User's Guide (E39546-005) is also available for download from Intel's support web site: <http://support.intel.com/support/motherboards/server/s5520SC/>
- Quick Reference Label – update from E39547-002 to E39547-004
 - Add Dolby Home Theater adhesive logo
- Intel® Server Management Software (ISMS) DVD - update from 3.1 to 3.5

Customer Impact of Change and Recommended Action:

Intel does not expect any customer impact to these changes.

Products Affected / Intel Ordering Codes:

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA
S5520HC	900402	900402	E42762-406	E42762-407
S5500HCV	902386	902386	E42763-402	E42763-403
S5520SC	900963	900963	E42764-303	E42764-304

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

June 25, 2009

Revision Number:

00

Reason:

Originally Published PCN