



Product Change Notification

109713 - 02

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2010. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109713 - 02
Change Title: Intel(R) Server Board S3420GPLX, Intel(R) Server Board S3420GPLC, Intel(R) Server System SR1630GP, Intel(R) Server System SR1630HGP, PCN 109713-02, Product Design, Update BIOS, BMC and FRUSDR; Update the materials in the boxed board and system package, Reason for Revision: To remove the change to the Resource CD
Date of Publication: January 21, 2010

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Feb 05, 2010
---	--------------

Description of Change to the Customer:

Reason for Revision: To remove the change to the Resource CD

Intel is updating new MM#'s for Intel(R) Server Board S3420GPLX and S3420GPLC, Intel® Server System SR1630GP and SR1630HGP to support Intel® Core(TM) i3 processors i3-530, i3-540 and Intel® Pentium® processor G6950.

The motherboards and the systems carrying the motherboard have implemented below change: the software package is updated to BIOS 35, BMC 01.17 and FRUSDR 17. The system software update package, including Release notes for each, will be available for download from Intel's support website <http://www.intel.com/support/motherboards/server/s3420gp/> prior to this change.

Please see software release notes for a list of changes when available.

Other change:

The OEM 10-pack with product order code BB3420GPLC will add one Attention Doc with IPN E87713-001 to this package.

Customer Impact of Change and Recommended Action:

Intel does not foresee any adverse customer impact from these changes. Intel recommends that the customer perform a standard level of evaluation as updated product and software become available.

The customer can order the affected products with the new MM#'s.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change Product Code	Post Change MM#	Post Change TA	Post Change PBA
S3420GPLX 902720	902720	E74800- 402	E51974- 402	S3420GPLX	907525	E74800- 403	E51974- 403
S3420GPLC 902723	902723	E77963- 402	E51976- 402	S3420GPLC	907524	E77963- 403	E51976- 403
BB3420GPLC 902727	902727	E77963- 402	E51976- 402	BB3420GPLC	907526	E77963- 403	E51976- 403
SR1630GP 902731	902731	E65196- 004		SR1630GP	907506	E65196- 005	
SR1630HGP 902732	902732	E65540- 004		SR1630HGP	907517	E65540- 005	
SR1630HGPNA 902734	902734			SR1630HGPNA	905819		
SR1630GPNA 902735	902735			SR1630GPNA	905769		

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

November 24, 2009

00

Originally Published PCN

January 7, 2010

01

BIOS Release Delay

January 21, 2010

02

To remove the change to the Resource CD