



Product Change Notification

110914 - 01

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2011. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 110914 - 01
Change Title: Intel (R) Server Board S1200BTS, PCN 110914-01, Product Material, Update Software Stack; Change CPU protective cover; Reason for Revision: Fix the wording
Date of Publication: November 10, 2011

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Aug 26, 2011
-------------------------------------------------------------------------	--------------

Description of Change to the Customer:

Reason for Revision: Update the change reason

Description of Change to the Customer:

Intel is making the following changes on the Intel(R) Server Board S1200BTS:

- 1) Updating the CPU protective cover to reduce the possibility of socket pin damage. Below is a picture of the new CPU protective cover :



- 2) Updating the server board to BIOS revision 29. The new BIOS including release notes with a list of BIOS changes will be available for download from Intel's support site:
<http://downloadcenter.intel.com/SearchResult.aspx?lang=eng&ProductFamily=Server+Products&ProductLine=Intel%c2%ae+Server+Boards&ProductProduct=Intel%c2%ae+Server+Board+S1200BT&ProdId=3326&LineId=3161&FamilyId=37> prior to this change.

Customer Impact of Change and Recommended Action:

The change of the CPU protective cover has no functional impact but may require manufacturing process changes when assembling a CPU in the server board. Intel recommends that the customer perform a standard level of evaluation as the updated product and software become available.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change Product Code	Post Change MM#	Post Change TA	Post Change PBA
BBS1200BTS	911649	G27776-306	E98683-306	BBS1200BTS	911649	G27776-307	E98683-307
S1200BTS	911786	G27776-306	E98683-306	S1200BTS	911786	G27776-307	E98683-307
DBS1200BTS	911808	G27776-306	E98683-306	DBS1200BTS	911808	G27776-307	E98683-307

PCN Revision History:

Date of Revision:

August 10, 2011
November 10, 2011

Revision Number:

00
01

Reason:

Originally Published PCN
Fix the wording