



# Product Change Notification

## 108975 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jcb.ijkk@intel.com](mailto:jcb.ijkk@intel.com)

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 108975 - 00  
**Change Title:** DP35DP, PCN 108975-00, Product Design, Audio Codec change and BIOS update  
**Date of Publication:** November 12, 2008

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Dec 04, 2008
---	--------------

## Description of Change to the Customer:

The audio codec 9271D stepping A2 is being EOLed by the vendor and will be replaced with the B4 stepping at reference location U1AU.

Update BIOS to DPP3510J.86A.0497

Please refer to the release notes posted at

<http://developer.intel.com/products/motherboard/DP35DP/tools.htm>

## Customer Impact of Change and Recommended Action:

For those customers that have disk image, this change to the codec has been observed to report a "New device detected". Microsoft\* Windows will display a message and automatically install the necessary drivers; however customers may wish to update their disk image to avoid the message.

These changes are not expected to cause a change to the Microsoft\* Windows\* operating system's software driver stack.

It is recommended that customers evaluate this new BIOS to ensure a smooth transition. This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. Intel is not recommending additional qualification of these changes on platforms received from Intel.

## Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change AA	Post Change AA
BOXDP35DPM	888155	D81073-210	D81073-211
BLKDP35DPM	888160	D81073-210	D81073-211

## **PCN Revision History:**

**Date of Revision:**

November 12, 2008

**Revision Number:**

00

**Reason:**

Originally Published PCN