



Product Change Notification

110781 - 01

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2011. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 110781 - 01
Change Title: Intel® Server Chassis P4304XXSHCN, Single, Intel® Server System P4304BTLSHCN, Single, Intel® Server System R1304BTLSHBN, Single, PCN 110781-01, Product Design, Product Material, Update SGPIO cable, Reason for Revision: Update the TA number and update the projected date
Date of Publication: August 02, 2011

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Aug 19, 2011
---	--------------

Description of Change to the Customer:

Reason for Revision: Update the TA number and update the projected date

Intel will implement the following changes on Intel(R) Server System R1304BTLSHBN:

1. Updating the Serial General Purpose Input/Output (SGPIO) cable from Intel® Part Number (IPN): E98573-001 to IPN: G10943-001. The new updated SGPIO cable is Y type cable. It can both support 5-pin to 4-pin and 5-pin to 5-pin connectors. For the detail information, please refer to TA-0977-01.

The following changes are on Intel(R) Server System P4304BTLSHCN and Intel(R) Server Chassis P4304XXSHCN:

1. Update the cable from IPN number: G22461-002 to IPN number: G22461-003. The new updated SGPIO cable is Y type cable. It can both support 5-pin to 4-pin and 5-pin to 5-pin connectors. For the detail information, please refer to TA-0977-01.

Customer Impact of Change and Recommended Action:

Intel recommends customers evaluate the changes and determine impacts to their specific applications when the updated products become available.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Post Change Product Code	Post Change MM#	Post Change TA
R1304BTLSHBN	911688	G19777-002	R1304BTLSHBN	911688	G19777-003
P4304XXSHCN	911765	TBD	P4304XXSHCN	911765	TBD
P4304BTLSHCN	912775	TBD	P4304BTLSHCN	912775	TBD
R1304BTLSHBNNNA	907658	G19777-002	R1304BTLSHBNNNA	907658	G19777-002
P4304BTLSHCNNA	907886	TBD	P4304BTLSHCNNA	907886	TBD
P4304XXSHCNNA	907812	TBD	P4304XXSHCNNA	907812	TBD

PCN Revision History:

Date of Revision:

June 28, 2011

August 2, 2011

Revision Number:

00

01

Reason:

Originally Published PCN

Update the TA number and update the projected date