



Product Change Notification

Change Notification #: 114685 - 00
Change Title: Intel® NUC Kit, NUC6i7KYK,
PCN 114685-00, Product Design, Product
Material,
Bios and Firmware Update
Date of Publication: June 14, 2016

Key Characteristics of the Change:

Product Design, Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jul 01, 2016
---	--------------

Description of Change to the Customer:

The Intel® NUC Kit, NUC6i7KYK SKUs listed in the products affected table below will have the following changes.

1. The BIOS will be updated from KYSKLI70.86A.0034 to KYSKLI70.86A.0037. To access the release notes or get a copy of the BIOS for evaluation, go to <http://downloadcenter.intel.com>.
2. The HDMI Firmware will be updated from 0x1D to 0x20. The HDMI FW update will improve audio performance when connected to 5.1 and 7.1 HDMI 2.0 audio receivers and amplifiers.
3. The VESA mounting screws length will be increased.

Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure there is no quality, reliability, or functional implication to our customers. Intel is not recommending additional qualification of these changes on platforms received from Intel.

Intel will attempt to deplete pre-conversion material before shipping post-conversion material but there is a possibility of Intel shipping mixed inventory. Therefore, customers will need to manage and migrate to the post-conversion material as soon as possible.

Milestone dates are estimates and subject to change based on business and operational conditions.

Please contact your local Intel Field Sales Rep if you have any further questions about these changes.

Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change SA	Pre Change AA	Post Change SA	Post Change AA
BOXNUC6I7KYK	944578	H90754-102	H90766-403	H90754-103	H90766-404
BOXNUC6I7KYK1	944579	H90755-102	H90766-403	H90755-103	H90766-404
BOXNUC6I7KYK2	944580	H90756-102	H90766-403	H90756-103	H90766-404
BOXNUC6I7KYK3	944581	H90757-102	H90766-403	H90757-103	H90766-404
BOXNUC6I7KYK4	944582	H90758-102	H90766-403	H90758-103	H90766-404

PCN Revision History:**Date of Revision:**

June 14, 2016

Revision Number:

00

Reason:

Originally Published PCN



Product Change Notification

114685 - 00

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2016. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.