



# **Product Change Notification**

## **112952 - 02**

**INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.**

**A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.**

**Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.**

**The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.**

**Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.**

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific/PRC Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

**Copyright © Intel Corporation 2014. Other names and brands may be claimed as the property of others.**

**BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.**

**Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.**



# Product Change Notification

<b>Change Notification #:</b>	<b>112952 - 02</b>
<b>Change Title:</b>	<b>Intel® 82546GB Gigabit Ethernet Controller ( FW82546GB MM# 855352 Tray and MM# 855365 Tape) Intel® 82541PI Gigabit Ethernet Controller ( GD82541PI MM# 857512 Tape and 857520 Tray) Intel® 82541PI Gigabit Ethernet Controller ( GD82541PR MM# 857514 Tray and MM# 857515 Tape) Intel® 82541PR Gigabit Ethernet Controller ( GD82541ER MM# 858265 Tray and MM#858266 Tape) Intel® 82567LM Gigabit Ethernet PHY ( HG82567LM MM# 896265 Tray)</b>  <b>PCN 112952-02</b>  <b>Product Discontinuance</b>  <b>End Of Life</b>  <b>Reason for Revision: Correction to 2 Recommended Replacement SKUs.</b>
<b>Date of Publication:</b>	<b>June 12, 2014</b>

## Key Characteristics of the Change:

Product Discontinuance

## Forecasted Key Milestones:

<b>Last Product Discontinuance Order Date:</b>	Mar 31, 2015
<b>Orders are Non-Cancelable and Non-Returnable After:</b>	Mar 31, 2015
<b>Last Product Discontinuance Shipment Date:</b>	Sep 30, 2015

## Description of Change to the Customer:

### Reason for Revision: Correction to 2 Recommended Replacement SKUs.

Intel will be discontinuing these controllers due to the natural decline in demand for these products.

### Customer Impact of Change and Recommended Action:

Customers should review their demand forecasts and plan accordingly to place all orders by the Last Order Date of March 31, 2015, and plan for receipt of all shipments no later than Sept. 30, 2015.

Supply may be limited based on business conditions that may require either pull in or extension of the LOD/LSD at Intel's sole discretion. Orders after March 31, 2015 are Non-cancelable and Non-Returnable. There are replacement SKUs that are available, but may require customer requalification, so customers are encouraged to work closely with their local Intel Sales representatives to plan for a smooth transition including any final purchases to support customer-sponsored repair or warranty beyond the terms of this PDN. Intel recommends customers migrate new designs to the lead-free replacement SKUs identified.

### Products Affected / Intel Ordering Codes:

Marketing Name	Product Code	S-Spec	MM#	Stepping	Recommended Replacement Product Code	Recommended Replacement MM#
Intel® 82546GB Gigabit Ethernet Controller (Tray)	FW82546GB		855352	A0	NH82546GB	867764
Intel® 82546GB Gigabit Ethernet Controller (Tape)	FW82546GB	S L75S	855365	A1	NH82546GB	867767
Intel® 82541PI Gigabit Ethernet Controller (Tape)	GD82541PI	S L7AT	857512	C1	LU82541PI	860579
Intel® 82541PI Gigabit Ethernet Controller (Tray)	GD82541PR	S STD	857514		LU82541ER	862931
Intel® 82541PI Gigabit Ethernet Controller (Tape)	GD82541PR	S L7AU	857515		LU82541ER	862930
Intel® 82541PI Gigabit Ethernet Controller (Tray)	GD82541PI	S N/A	857520	C1	LU82541PI	860575
Intel® 82541PR Gigabit Ethernet Controller (Tray)	GD82541ER		858265	C0	<a href="#">LU82541ER</a>	<a href="#">862931</a>
Intel® 82541PR Gigabit Ethernet Controller (Tape)	GD82541ER	S L7CR	858266	C0	LU82541ER	862930
Intel® 82567LM Gigabit Ethernet PHY (Tray)	HG82567LM	S LAVY	896265	B0	<a href="#">WG82567LM</a>	<a href="#">896256</a>

### PCN Revision History:

Date of Revision:	Revision Number:	Reason:
March 24, 2014	00	Originally Published PCN
March 28, 2014	01	Change to Last Ship Date and Orders Non-Cancelable and Non-Returnable date.
<a href="#">June 12, 2014</a>	<a href="#">02</a>	<a href="#">Correction to 2 Recommended Replacement SKUs.</a>