



Product Change Notification

107506 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jcb.ijkk@intel.com

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107506 - 00
Change Title: DP965LT, PCN 107506-00, Product Design, BIOS update, power supply compatibility improvements and add alternate part to improve manufacturability
Date of Publication: April 25, 2007

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	May 10, 2007
---	--------------

Description of Change to the Customer:

1. Updated BIOS to version MQ96510J.86A.1676. Please refer to <http://www.intel.com/products/motherboard/dp965lt/tools.htm> for release notes.
2. Improved board power design to increase compatibility robustness with wider range of power supply units.
3. Added alternate part to improve manufacturability.

Customer Impact of Change and Recommended Action:

The changes have been thoroughly evaluated to ensure there is no quality, reliability or functional impact to customers.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change AA	Post Change AA
BLKDP965LTCK 888277	888277	D45921-105	D41694-209	D41694-210
BOXDP965LTCK 888278	888278	D45929-105	D41694-209	D41694-210

PCN Revision History:

Date of Revision: April 25, 2007	Revision Number: 00	Reason: Originally Published PCN
--	-------------------------------	--