



# Product Change Notification

## 113465 - 01

**INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.**

**A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.**

**Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.**

**The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.**

**Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.**

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific/PRC Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

**Copyright © Intel Corporation 2015. Other names and brands may be claimed as the property of others.**

**BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.**

**Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.**



# Product Change Notification

<b>Change Notification #:</b>	<b>113465 - 01</b>
<b>Change Title:</b>	<b>Intel® 82571EB Gigabit Ethernet Controller, T&amp;R HL82571EB MM#916298, Intel® 82571EB Gigabit Ethernet Controller, Tray HL82571EB MM#916297, Intel® 82572EI Gigabit Ethernet Controller, T&amp;R HL82572EI MM#916300, Intel® 82572EI Gigabit Ethernet Controller, Tray HL82572EI MM#916299, Intel® 82576EB Gigabit Ethernet Controller, T&amp;R HL82576EB MM#916949, Intel® 82576EB Gigabit Ethernet Controller, Tray, HL82576EB MM#916950</b>  <b>PCN 113465-01</b>  <b>Product Discontinuance</b>  <b>End of Life</b>  <b>Reason for Revision: Milestone changed from ONC to NCNR and associated date and text</b>
<b>Date of Publication:</b>	<b>February 13, 2015</b>

## Key Characteristics of the Change:

Product Discontinuance

## Forecasted Key Milestones:

<b>Last Product Discontinuance Order Date:</b>	Dec 01, 2015
<b>Orders are Non-Cancelable and Non-Returnable After:</b>	<b>Dec 01, 2015</b>
<b>Last Product Discontinuance Shipment Date:</b>	May 31, 2016

## Description of Change to the Customer:

### Reason for Revision: Milestone changed from ONC to NCNR and associated date and text

Intel will be discontinuing these controllers due to the natural decline in demand for these products.

### Customer Impact of Change and Recommended Action:

Customers should review their demand forecasts and plan accordingly to place all orders by the Last Order Date of December 1, 2015, and plan for receipt of all shipments no later than May 31, 2016. Supply may be limited based on business conditions that may require either pull in or extension of the LOD/LSD at Intel's sole discretion.

### Orders are Non-Cancelable and Non-Returnable after the Last Order Date of December 1, 2015.

There are replacement SKUs that are available, but may require customer requalification, so customers are encouraged to work closely with their local Intel Sales representatives to plan for a smooth transition including any final purchases to support customer-sponsored repair or warranty beyond the terms of this PDN. Intel recommends customers migrate new designs to the lead-free replacement SKUs identified.

### Products Affected / Intel Ordering Codes:

Marketing Name	Product Code	S-Spec	MM#	Stepping	Recommended Replacement Product Code	S-Spec	Recommended Replacement MM#
Intel® 82571EB Gigabit Ethernet Controller	HL82571EB	S LJAY	916297	D1	JL82571EB	S LJB4	916663
Intel® 82571EB Gigabit Ethernet Controller	HL82571EB	S LJAZ	916298	D1	JL82571EB	S LJB5	916836
Intel® 82572EI Gigabit Ethernet Controller	HL82572EI	S LJB2	916299	D1	JL82572EI	S LJB8	916939
Intel® 82572EI Gigabit Ethernet Controller	HL82572EI	S LJB3	916300	D1	JL82572EI	S LJB9	916940
Intel® 82576EB Gigabit Ethernet Controller	HL82576EB	S LJBC	916949	A2	JL82576EB	S LJBG	916955
Intel® 82576EB Gigabit Ethernet Controller	HL82576EB	S LJBD	916950	A2	JL82576EB	S LJBH	916956

### PCN Revision History:

Date of Revision:	Revision Number:	Reason:
December 11, 2014	00	Originally Published PCN
February 13, 2015	01	Milestone changed from ONC to NCNR and associated date and text