



Product Change Notification

106928 – 02

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106928 - 02
Change Title: Intel® Pentium® M Processor, Intel® Celeron® M Processor, Intel® 910GML, Intel® 915GMS, & Intel® 915PM, PCN 106928-02, Product Discontinuance, Product Discontinuance, Reason for Revision: Updated Products Affected/Intel Ordering Codes Table
Date of Publication: December 27, 2006

Key Characteristics of the Change:

Product Discontinuance

Forecasted Key Milestones:

	Tray Processors & Chipsets	Boxed Processors
Product Discontinuance Program Support Begins:	Nov 06, 2006	Nov 06, 2006
Orders for Discontinued Products Become Non-Cancelable:	Jan 05, 2007	Jan 05, 2007
Product Discontinuance Demand To Local Intel Representative:	Jan 05, 2007	Not Applicable
Last Corporate Commit Product Hot List Date:	Feb 23, 2007	Feb 23, 2007
Last Product Discontinuance Order Date:	Mar 09, 2007	Mar 09, 2007
Last Product Discontinuance Shipment Date:	May 02, 2008	Jun 08, 2007

Description of Change to the Customer:

Reason for Revision: Updated the Products Affected/Intel Ordering Codes for the Intel® Pentium® M Processor & Intel® Celeron® M Processors product table.

Reason for Revision: Removed the Intel® Celeron® Processor 360 from the affected product list. This product has been discontinued from a previous PCN.

Market demand for the Intel® processors and Chipsets indicated on this notification has shifted to other Intel® products. The products identified in this notification will be discontinued and unavailable for additional orders after the "Last Product Discontinuance Order Date" (see "Key Milestones" above).

The following products will be moving to the Infrastructure Processor Division for continued support of Embedded Intel Architecture customers. For Intel Architecture based customers, please note that the Key Milestones listed above will apply in determining your remaining demand and placing your last orders.

A Product Support Notification, PCN 107091-01 has recently been published for these products: Intel® Pentium® M Processor 760 (867109), Intel® Pentium® M Processor 760 (864656), Intel® Pentium® M Processor 760 (864683), Intel® Celeron® Processor 370 (872126), Intel® Celeron® Processor 370 (872299), Intel®

Celeron® Processor 370 (872115), Intel® 915GM (870319), Intel® 915GM LF (870323)

Customer Impact of Change and Recommended Action:

Please determine your remaining demand for these products and place your "Last Product Discontinuance Orders" in accordance with the "Key Milestones" listed above. Products listed on the "Products Affected/Intel Ordering Codes" table below will remain on Intel's Corporate Commit Process until the "Last Product Discontinuance Order Date."

Boxed processors will not be available after boxed inventory is depleted (see "Key Milestones" above.) Intel is offering tray processors to Intel Authorized Distributors as a substitute for depleted boxed processor inventory. Substitute tray processors are identified below in the "Boxed Processors Product Table."

Products Affected / Intel Ordering Codes:

Intel® 910GML, Intel® 915GMS, & Intel® 915PM				
Marketing Name	Product Code	S-Spec	MM#	Stepping
Intel® 915PM	NQ82915PM	S L8G3	870320	C-1
Intel® 915GMS	NQ82915GMS	S L8G4	870321	C-1
Intel® 910GML	NQ82910GML	S L8G5	870322	C-1
Intel® 915PM LF	QG82915PM	S L8G7	870324	C-1
Intel® 910GML LF	QG82910GML	S L8G8	870326	C-1
Intel® 915GMS LF	QG82915GMS	S L8G9	870327	C-1

Intel® Pentium® M Processor & Intel® Celeron® M Processor Tray						
Marketing Name	Processor#	Frequency	Product Code	S-Spec	MM#	Stepping
Intel® Pentium® M Processor	740	1.73 GHz	RJ80536GE0302M	S L7S8	863511	C-0
Intel® Pentium® M Processor	740	1.73 GHz	RH80536GE0302M	S L7SA	863512	C-0
Intel® Pentium® M Processor	770	2.13 GHz	RH80536GE0462M	S L7SL	864655	C-0
Intel® Pentium® M Processor	750	1.86 GHz	RH80536GE0362M	S L7S9	864659	C-0
Intel® Pentium® M Processor	770	2.13 GHz	RJ80536GE0462M	S L7SP	864682	C-0
Intel® Pentium® M Processor	780	2.26 GHz	RH80536GE0512M	S L7VB	864764	C-0
Intel® Pentium® M Processor	770	2.13 GHz	LE80536GE0462M	S L868	867100	C-0
Intel® Pentium® M Processor	750	1.86 GHz	LE80536GE0362M	S L86A	867110	C-0
Intel® Pentium® M Processor	740	1.73 GHz	LE80536GE0302M	S L86B	867113	C-0
Intel® Pentium® M Processor	753	1.2 GHz	RJ80536UC0092M	S L8JQ	871529	C-0
Intel® Pentium® M Processor	733	1.1 GHz	RJ80536UC0052M	S L8JR	871530	C-0
Intel® Pentium® M Processor	773	1.3 GHz	LE80536UC0132M	S L8LR	871717	C-0
Intel® Pentium® M Processor	753	1.2 GHz	LE80536UC0092M	S L8LS	871718	C-0
Intel® Pentium® M Processor	733	1.1 GHz	LE80536UC0052M	S L8LT	871719	C-0
Intel® Pentium® M Processor	773	1.3 GHz	RJ80536UC0132M	S L8LK	871720	C-0
Intel® Pentium® M Processor	753	1.2 GHz	RJ80536UC0092M	S L8LL	871721	C-0
Intel® Pentium® M Processor	733	1.1 GHz	RJ80536UC0052M	S L8LM	871722	C-0
Intel® Pentium® M Processor	778	1.6 GHz	RJ80536LC0252M	S L8QF	872682	C-0
Intel® Pentium® M Processor	778	1.6 GHz	LE80536LC0252M	S L8QG	872683	C-0
Intel® Pentium® M Processor	780	2.26 GHz	LE80536GE0512M	S L8QK	873067	C-0
Intel® Celeron® M Processor	383	1 GHz	LE80536VC0011M	S L8LV	871727	C-0
Intel® Celeron® M Processor	383	1 GHz	RJ80536VC0011M	S L8LP	871769	C-0
Intel® Celeron® M Processor	380	1.6 GHz	LE80536NC0251M	S L8MU	872113	C-0
Intel® Celeron® M Processor	390	1.7 GHz	LE80536NC0291M	S L8MV	872114	C-0
Intel® Celeron® M Processor	390	1.7 GHz	RH80536NC0291M	S L8MP	872119	C-0

Intel® Celeron® M Processor	380	1.6 GHz	RH80536NC0251M	S L8MN	872120	C-0
Intel® Celeron® M Processor	390	1.7 GHz	RJ80536NC0291M	S L8MH	872124	C-0
Intel® Celeron® M Processor	380	1.6 GHz	RJ80536NC0251M	S L8MG	872125	C-0

Intel® Pentium® M Processor & Intel® Celeron® M Processor Box

Boxed Processors Marketing Name	Boxed Processors Processor#	Boxed Processors Frequency	Boxed Processors Product Code	Boxed Processors S-Spec	Boxed Processors MM#	Boxed Processors Stepping	Substitute Tray Processors Product Code	Substitute Tray Processors S-Spec	Substitute Tray Processors MM#	Substitute Tray Processors Stepping
Intel® Celeron® M Processor	370	1.5 GHz	BX80536NC1500EJ	S L86J	868601	C-0	RH80536NC0211M	SL8MM	872299	C-0
Intel® Pentium® M Processor	780	2.26 GHz	BX80536GE2266FJ	S L7VB	868604	C-0	RH80536GE0512M	S L7VB	864764	C-0
Intel® Pentium® M Processor	770	2.13 GHz	BX80536GE2133FJ	S L7SL	868605	C-0	RH80536GE0462M	S L7SL	864655	C-0
Intel® Pentium® M Processor	760	2 GHz	BX80536GE2000FJ	S L7SM	868606	C-0	RH80536GE0412M	S L7SM	864656	C-0
Intel® Pentium® M Processor	750	1.86 GHz	BX80536GE1866FJ	S L7S9	868607	C-0	RH80536E0362M	S L7S9	864659	C-0
Intel® Pentium® M Processor	740	1.73 GHz	BX80536GE1733FJ	S L7SA	868608	C-0	RH80536E0302M	S L7SA	863512	C-0
Intel® Celeron® M Processor	390	1.7 GHz	BX80536NC1700EJ	S L8MP	874315	C-0	RH80536NC0291M	SL8MP	872119	C-0
Intel® Celeron® M Processor	380	1.6 GHz	BX80536NC1600EJ	S L8MN	874325	C-0	RH80536NC0251M	SL8MN	872120	C-0
Intel® Celeron® M Processor	370	1.5 GHz	BX80536NC1500EJ	S L8MM	874326	C-0	RH80536NC0211M	SL8MM	872299	C-0

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

November 7, 2006

00

Originally Published PCN

December 19, 2006

01

Updated Intel Celeron Processor
affected product list

December 27, 2006

02

Updated the Products
Affected/Intel Ordering Codes
for the Intel® Pentium® M
Processor & Intel® Celeron® M
Processors product table.