



Product Change Notification

108363 - 04

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 108363 - 04

Change Title: S3200SH; S3210SH, PCN 108363-04, Product Design, BIOS and Firmware update for Intel® Xeon® processor series 3100 and 3300 C1 stepping support, Reason for Revision: move BMC memory change to PCN108565-00

Date of Publication: June 15, 2008

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jul 07, 2008
---	--------------

Description of Change to the Customer:

Reason for Revision: move BMC memory change to PCN108565-00

The BIOS will roll to revision 42 to support Intel® Xeon® 3100 and 3300 series C1 stepping processors. Please see the BIOS release notes for details of other changes made. The Firmware will roll to revision 00.29, please see the Firmware release notes for details of changes made. The FRU/SDR will roll to revision 1.12, please see the FRUSDR release notes for details of changes made. The NIC EEPROM image will roll to revision 1.2 to correct a Serial Over LAN issue. A board FAB change is being made to improve quality and manufacturability. The floppy cable is being removed from the boxed board SKU's (S3200SHV and S3210SHLC).

Customer Impact of Change and Recommended Action:

Customer may want to perform re-qualification, re-test, recertification.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change MM#	Post Change TA	Post Change PBA
S3200SHV S5	892449	E12678-206	D86141-206	897886	E12678-301	D86141-301
BSHBBL	892502	E15110-	D86140-	897887	E15110-	D86140-

892502		206	206		301	301
BSHBBV 892541	892541	E15111- 206	D86141- 206	897885	E15111- 301	D86141- 301
BSHBBLC 892605	892605	E15109- 206	D86139- 206	897891	E15109- 301	D86139- 301
S3210SHLC 892695	892695	E12677- 206	D86139- 206	897888	E12677- 301	D86139- 301

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

March 28, 2008

00

Originally Published PCN

April 2, 2008

01

Remove floppy cable from boxed board sku's (S3200SHV, S3210SHLC, S3210SHLX).

May 16, 2008

02

change BIOS to rev.42

June 9, 2008

03

S3200SHV MM# rolls to 897886

June 15, 2008

04

move BMC memory change to PCN108565-00