



# **Product Change Notification**

## **112800 - 01**

**INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.**

**A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.**

**Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.**

**The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.**

**Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.**

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific/PRC Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

**Copyright © Intel Corporation 2013. Other names and brands may be claimed as the property of others.**

**BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.**

**Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.**



# Product Change Notification

**Change Notification #:** 112800 - 01  
**Change Title:** Intel® Server System P4308RPLSHDR, R1208RPMSHOR, R1208RPOSHOR, R1304RPMSHOR, R1304RPOSHBN and R1304RPSSFBN  
PCN 112800-00, Product Design  
Update BIOS/ME/BMC/FRUSDR Firmware and DVD  
**Reason for Revision: Correct Pre-Change TA# for Product Code R1304RPSSFBN, MM#930699**  
**Date of Publication:** January 29, 2014

**Key Characteristics of the Change:**  
Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Feb 28, 2014
---	--------------

*\* Intel appreciates the customer's desire to receive the latest revision of products. However, Intel manages inventory on a first in first out (FIFO) basis at the MM# level. Subsequently, customer requests for a specific revision of material (below the MM#) will not be supported by Intel.*

## Description of Change to the Customer:

**Reason for Revision: Correct Pre-Change TA# for Product Code R1304RPSSFBN, MM#930699**

Intel will implement the following changes on Intel® Server System R1000RP and P4000RP series:

1. Update the BIOS from revision 01.03.0004 to 01.04.0002 to support more processors. BIOS 01.04.0002 is contains feature enhancements and fixes. Please refer to the BIOS release notes for further information.
2. Update the Manageability Engine (ME) firmware from revision 03.00.04.209 to 03.00.05.068
3. Update the Integrated Baseboard Management Controller (BMC) firmware from revision 01.08 to 01.10
4. Update the FRUSDR from revision 1.05 to 1.06.

5. Add DVD space Mylar to front end of Intel® Server System R1304RPMSHOR and R1304RPOSHBN for mechanical assembling. See image below:



### Customer Impact of Change and Recommended Action:

Intel recommends that the customer perform a standard level of evaluation. Customers can check the latest software package at <http://www.intel.com/support>.

Customers need to place future orders using the new Order Code (Post Change MM#) as noted in below table.

### Products Affected / Intel Ordering Codes:

Product Code	Pre Change MM#	Pre Change TA	Post Change MM#	Post Change TA
R1208RPOSHOR	927916	G89575-002	934321	G89575-003
R1208RPMSHOR	927917	G83358-003	934323	G83358-004
P4308RPLSHDR	927918	G70373-005	934320	G70373-006
R1304RPMSHOR	930261	G97216-002	934324	G97216-003
R1304RPSSFBN	930699	<b>G73185-004</b>	934319	G73185-005
R1304RPOSHBN	930733	G70453-004	934322	G70453-005

### PCN Revision History:

**Date of Revision:**

December 26, 2013

**January 29, 2014**

**Revision Number:**

00

**01**

**Reason:**

Originally Published PCN

**Correct Pre-Change TA# for  
Product Code R1304RPSSFBN,  
MM#930699**