



Product Change Notification

113232 - 01

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jcb.ijkk@intel.com

Copyright © Intel Corporation 2014. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #:	113232-01
Change Title:	Intel® Ethernet Server Adapter I350-T2, OEM Gen (Stony Lake DT) MM#914225 Intel® Ethernet Server Adapter I350-T2, retail bulk (Stony Lake DT) MM#914222 Intel® Ethernet Server Adapter I350-T2, retail unit (Stony Lake DT) MM#914221 Intel® Ethernet Server Adapter I350-T4, OEM Gen (Stony Lake QT) MM#914226 Intel® Ethernet Server Adapter I350-T4, retail bulk (Stony Lake QT) MM#914224 Intel® Ethernet Server Adapter I350-T4, retail unit (Stony Lake QT) MM#914223 PCN 113232-01 Product Discontinuance End of Life Revision: Incorrect Replacement MM#
Date of Publication:	September 24, 2014

Key Characteristics of the Change:

Product Discontinuance

Forecasted Key Milestones:

Last Product Discontinuance Order Date:	Feb 14, 2015
Last Product Discontinuance Shipment Date:	Aug 14, 2015

Description of Change to the Customer:

Reason for Revision: Incorrect Replacement MM#

The Intel® Ethernet Server Adapter I350-T2 and Intel® Ethernet Server Adapter I350-T4 will undergo the following changes:

1. Existing Product is being EOLed to be replaced with new versions which have the AUX Power component changes that will result in a decrease of in-rush current during power supply start-up. Product functionality does not change.

Customer Impact of Change and Recommended Action:

The new versions of the Intel® Ethernet Server Adapter I350-T2 and Intel® Ethernet Server Adapter I350-T4 have been fully tested, qualified and approved by Intel. Intel anticipates no impact to the customer.

Customers should place their Last Time Orders by February 14, 2015 and delivery of all orders must be taken no later than August 14, 2015. The recommended replacement SKUs are noted within the affected products table within this PCN notice, however, customers should validate the replacement SKUs prior to replacement usage. Customers should place future orders after (02/14/15) using the new order codes.

Please contact your local Intel Field Sales Rep if you have any further questions about these changes.

Products Affected / Intel Ordering Codes:

Product Name	Product Code	Affected MM#	Recommended Replacement Product Code	Recommended Replacement MM#
Intel® Ethernet Server Adapter I350-T2 (Stony Lake DT)	I350T2	914221	I350T2V2	936711
Intel® Ethernet Server Adapter I350-T2 (Stony Lake DT)	I350T2BLK	914222	I350T2V2BLK	936714
Intel® Ethernet Server Adapter I350-T4 (Stony Lake QT)	I350T4	914223	I350T4V2	934615 936715
Intel® Ethernet Server Adapter I350-T4 (Stony Lake QT)	I350T4BLK	914224	I350T4V2BLK	936716
Intel® Ethernet Server Adapter I350-T2 (Stony Lake DT)	I350T2G1P20	914225	I350T2G2P20	934607
Intel® Ethernet Server Adapter I350-T4 (Stony Lake DT)	I350T4G1P20	914226	I350T4G2P20	934608

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
September 3, 2014	00	Originally Published PCN
September 24, 2014	01	Incorrect Replacement MM#