



Product Change Notification

Change Notification #: 114869 - 01

Change Title: Intel® NUC Kit, NUC6i3SYH,
Intel® NUC Kit, NUC6i3SYK,
Intel® NUC Kit, NUC6i5SYH,
Intel® NUC Kit, NUC6i5SYK,
PCN 114869-01, Product Design,
Product Material,
BIOS Update and DIMM socket
modification,
Reason for Revision: SODIMM
socket modification

Date of Publication: September 12, 2016

Key Characteristics of the Change:

Product Design, [Product Material](#)

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Sep 19, 2016
---	--------------


Description of Change to the Customer:

Reason for Revision: SODIMM socket modification


The Intel® NUC Kit SKUs listed in the products affected table below will have the following change.

1. The BIOS will be updated from SYSKLI35.86A.0042 to SYSKLI35.86A.0051. To access the release notes or get a copy of the BIOS for evaluation, go to <http://downloadcenter.intel.com>.
2. The SODIMM socket is being modified. The latch stopper structure will limit the latch during mating and un-mating of the DIMM. See picture below

Before



After



Customer Impact of Change and Recommended Action:

It is recommended that customers evaluate this new BIOS to ensure a smooth transition. This change has been thoroughly evaluated to ensure that there are no quality or reliability implications to our customers. Intel validation of a new board revision does not include testing with older versions of BIOS.

The change to the SODIMM socket is not expected to impact the product.

Milestone dates are estimates and subject to change based on business and operational conditions. Please contact your local Intel Field Sales Rep if you have any further questions about these changes.

Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change SA	Pre Change AA	Post Change SA	Post Change AA
BOXNUC6I5SYK	943204	H87089-504	H81131-504	H87089-505	H81131-505
BOXNUC6I5SYH	943207	H87090-504	H81131-504	H87090-505	H81131-505
BOXNUC6I3SYH	943209	H87086-504	H81132-504	H87086-505	H81132-505
BOXNUC6I3SYK	943211	H87085-504	H81132-504	H87085-505	H81132-505
BOXNUC6I5SYKL	946869	H95046-504	H81131-504	H95046-505	H81131-505
BOXNUC6I5SYHL	946874	H95047-504	H81131-504	H95047-505	H81131-505
BOXNUC6I3SYKL	946878	H95044-504	H81132-504	H95044-505	H81132-505
BOXNUC6I3SYHL	946884	H95045-504	H81132-504	H95045-505	H81132-505

PCN Revision History:

Date of Revision:

September 2, 2016

[September 12, 2016](#)

Revision Number:

00

[01](#)

Reason:

Originally Published PCN

[SODIMM socket modification](#)



Product Change Notification

114869 - 01

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2016. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.