



# Product Change Notification

**Change Notification #: 114974 - 03**

**Change Title:** Select Intel® Server Boards, Intel® Server Systems, Intel® Compute Modules and Intel® Server Chassis Products, PCN 114974-03, Product Discontinuance, End of Life,  
**Reason for Revision: Revising recommended replacement product codes and MM Numbers for Intel® Server Boards and Intel® Server Systems and extended Forecasted Key Milestones.**

**Date of Publication: June 12, 2017**

## Key Characteristics of the Change:

Product Discontinuance

## Forecasted Key Milestones:

<b>Product Discontinuance Program Support Begins:</b>	Oct 30, 2016
<b>Orders are Non-Cancelable and Non-Returnable After:</b>	Jan 31, 2017
<b>Last Product Discontinuance Order Date*:</b>	<b>Jun 30, 2017</b>
<b>Last Product Discontinuance Shipment Date:</b>	<b>Oct 31, 2017</b>

\* Intel appreciates the customer's desire to receive the latest revision of products. However, Intel manages inventory on a first in first out (FIFO) basis at the MM# level. Subsequently, customer requests for a specific revision of material (below the MM#) will not be supported by Intel.

**Reason for Revision:** Revising recommended replacement product codes and MM Numbers for Intel® Server Boards and Intel® Server Systems and extended Forecasted Key Milestones.

## Description of Change to the Customer:

Intel Corporation is announcing the discontinuance of the Intel® Server Board S1200RPV3 family listed in the "Products Affected/Intel Ordering Codes" table below.

Final purchase orders are non-cancelable and non-returnable, notwithstanding any conflicting terms in our quotes, purchase order acknowledgment, or Distributor agreements.

Intel reserves the right to change the products because of material source restriction.

The products listed in the "Products Affected/Intel Ordering Codes" table below, have been discontinued, and will be unavailable for additional orders after the "Last Product Discontinuance Order Date" (see "Key Milestones" above) OR as soon as current inventories are depleted. All orders will be filled on a first-come, first-served basis. For applicable replacement product(s), please see the "Replacement Product" column in table below.

## Engineering and Support Guidance for Discontinued Products:

1. No new Operating System (OS), peripheral or adaptor validation is planned during the extended life period. The THOL, supported processor and tested memory lists are frozen at PDA.
2. No new features enhancements should be expected, however ECOs may be required during the extended life period to maintain supply lines (e.g. to qualify new vendor due to a component EOL).
3. Intel will provide reasonable commercial efforts in debugging issues during the warranty period for the product after the PDA date has passed. Fixes cannot be committed, but Intel will endeavor to provide reasonable workarounds for the product.

## Customer Impact of Change and Recommended Action:

Please determine your remaining demand for this product and/or evaluate additional sources (if applicable).

Lead-times on products with announced product discontinuance can typically stretch to 12 weeks and volumes are not buffered during the PDA period. Please work with your Intel representative on your quarterly demand forecast in order to reduce lead-times to 2-4 weeks.

Please contact your local Intel Sales Office or Distributor if you require more information or need assistance in selecting a replacement product.

Milestone dates are estimates and subject to change based on business and operational conditions.

## Products Affected / Intel Ordering Codes:

Product Name	Product Code	MM#	Recommended Replacement Product Code	Recommended Replacement MM#
Intel® Server Board S1200V3RPL	BBS1200V3RPL	942028	<a href="#">DBS1200SPLR</a>	951869
Intel® Server Board S1200V3RPS	BBS1200V3RPS	942030	<a href="#">DBS1200SPSR</a>	951870
Intel® Server Board S1200V3RPO	BBS1200V3RPO	942032	<a href="#">DBS1200SPOR</a>	951871
Intel® Server Board S1200V3RPM	BBS1200V3RPM	942034	<a href="#">DBS1200SPOR</a>	951871
Intel® Server Board S1200V3RPL	DBS1200V3RPL	942029	<a href="#">DBS1200SPLR</a>	951869
Intel® Server Board S1200V3RPS	DBS1200V3RPS	942031	<a href="#">DBS1200SPSR</a>	951870
Intel® Server Board S1200V3RPO	DBS1200V3RPO	942033	<a href="#">DBS1200SPOR</a>	951871
Intel® Server Board S1200V3RPM	DBS1200V3RPM	942037	<a href="#">DBS1200SPOR</a>	951871
Intel® Server System P4308RPLSHDR	P4308RPLSHDR	942047	N/A	N/A
Intel® Server System R1208RPMSHOR	R1208RPMSHOR	942046	R1208SPOSHOR	944477
Intel® Server System R1304RPSSFBN	R1304RPSSFBN	942044	R1304SPOSHBN	944471
Intel® Server System R1304RPMSHOR	R1304RPMSHOR	942045	R1304SPOSHOR	944476
Intel® Server System R1304RPOSHBN	R1304RPOSHBN	942043	R1304SPOSHBN	944471
System Maintenance Kit FR1304E3V3MSK	FR1304E3V3MSK	928727	N/A	N/A
System Electrical Spares Kit FR1304E3V3ESK	FR1304E3V3ESK	928728	N/A	N/A
Mini-SAS cable AXXE38DRVCBL	AXXE38DRVCBL	928729	N/A	N/A
SAS cable kit AXXE34DRVCBL	AXXE34DRVCBL	930878	N/A	N/A
I/O Shield for Intel® S1200V3RP Server Boards	AXXRPIOS	937292	N/A	N/A

## PCN Revision History:

Date of Revision:	Revision Number:	Reason:
October 27, 2016	00	Originally Published PCN
May 23, 2017	01	Updating the MM numbers for Intel® Server Boards.
May 31, 2017	02	Revising MM Numbers for Intel® Server Boards and Intel® Server Systems
<a href="#">June 12, 2017</a>	<a href="#">03</a>	<a href="#">Revising recommended replacement product codes and MM Numbers for Intel® Server Boards and Intel® Server Systems and extended Forecasted Key Milestones.</a>



# Product Change Notification

## 114974 - 03

**INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.**

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

**Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.**

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific/PRC Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2017. Other names and brands may be claimed as the property of others.

3D XPoint, Axxia, Basis, Basis Peak, BlueMoon, BunnyPeople, Celeron, Centrino, Cilk, Curie, Flexpipe, Intel, the Intel logo, Intel Atom, Intel CoFluent, Intel Core, Intel. Experience What's Inside, the Intel. Experience What's Inside logo, Intel Inside, the Intel Inside logo, Intel Insider, Intel Joule, Intel RealSense, Intel SingleDriver, Intel SpeedStep, Intel Unite, Intel vPro, Intel Xeon Phi, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Iris, Itanium, MCS, MMX, Optane, Ostro, Pali, Pentium, picoArray, Picochip, picoXcell, Puma, Quark, SMARTi, Soletta, Sound Mark, StarPro, Stay With It, the Engineering Stay With It logo, StreamSight, Tarari, The Journey Inside, Thunderbolt, the Thunderbolt logo, Transcende, True Key, Ultrabook, VTune, Xeon, X-GOLD, XMM, X-PMU and XPOSYS are trademarks of Intel Corporation or its subsidiaries in the U.S. and/or other countries.

Microsoft, Windows, and the Windows logo are trademarks, or registered trademarks of Microsoft Corporation in the United States and/or other countries. Java is a registered trademark of Oracle and/or its affiliates. Bluetooth is a trademark owned by its proprietor and used by Intel Corporation under license. Intel Corporation uses the Palm OS\* Ready mark under license from Palm, Inc. OpenCL and the OpenCL logo are trademarks of Apple Inc. used by permission by Khronos. Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.