



Product Change Notification

108299 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jcb.ijkk@intel.com

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 108299 - 00
Change Title: DP35DP, PCN 108299-00, Product Design, BIOS Update
Date of Publication: February 27, 2008

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Mar 20, 2008
---	--------------

Description of Change to the Customer:

Update BIOS to DPP3510J,86A.0407.

Please refer to the release notes posted at

<http://developer.intel.com/products/motherboard/DP35DP/tools.htm>

The BIOS default SATA will now be IDE from RAID, as in previous versions (within BIOS under "Advanced > Drive Configuration > Configure SATA as RAID").

The BIOS will incorporate the Intel® Rapid Recover Technology.

Customer Impact of Change and Recommended Action:

It is recommended that customers evaluate this new BIOS to ensure a smooth transition.

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. Intel is not recommending additional qualification of these changes on platforms received from Intel. This change is not expected to cause a change to the Microsoft* Windows* operating system's software driver stack.

There is no expected OS image change. However, system integrators who have built their OS image with RAID will need to change the BIOS setting (within BIOS under "Advanced > Drive Configuration > Configure SATA as") from IDE back to RAID before loading the image in their production line otherwise the image will fail. Intel recommends customers to use the Intel® Integrator Toolkit (iTK) to perform this task automatically. Please refer to <http://www.intel.com/go/itk> for more details on iTK.

Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change AA	Post Change AA
BOXDP35DPM	888155	D81073-207	D81073-208
BLKDP35DPM	888160	D81073-207	D81073-208
BOXDP35DPC	896408	E31208-207	E31208-208

PCN Revision History:

Date of Revision:

February 27, 2008

Revision Number:

00

Reason:

Originally Published PCN