



# Product Change Notification

## 113301 - 00

**INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.**

**A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.**

**Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.**

**The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.**

**Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.**

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific/PRC Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

**Copyright © Intel Corporation 2014. Other names and brands may be claimed as the property of others.**

**BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.**

**Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.**



# Product Change Notification

**Change Notification #:** 113301 - 00  
**Change Title:** Epoxy Material Change for Select Mobile Intel® Express Chipsets, Intel® Express Chipsets, and Intel® Chipsets, PCN 113301-00, Product Material  
**Date of Publication:** December 17, 2014

## Key Characteristics of the Change:

Product Material

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Jan 16, 2015
---	--------------

## Description of Change to the Customer:

Intel will be making a change in the epoxy material which will affect the transparency/color on select Mobile Intel® Express Chipsets, Intel® Express Chipsets, and Intel® Chipsets product identified in the Products Affected/Intel Ordering Codes table. Please see the illustrations and comments below:

<b>Current epoxy material:</b>  Epoxy color is deeper and non-transparent	
<b>New epoxy material:</b>  Epoxy color will be lighter and more transparent	

## Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers. This is a visual change only and will not affect the form, fit or function of the products listed below. Customers may receive shipments with current and new epoxy products until inventory has been depleted.

## Products Affected / Intel Ordering Codes:

Marketing Name	Stepping	Platform	Product Code	S-Spec	MM#
Intel® BD82QS67 Platform Controller Hub	B3	MOBILE	BD82QS67	S LJ4K	914323
Intel® BD82QM67 Platform Controller Hub	B3	MOBILE	BD82QM67	S LJ4M	914325
Intel® BD82HM65 Platform Controller Hub	B3	MOBILE	BD82HM65	S LJ4P	914377
Intel® BD82B65 Platform Controller Hub	B3	DESKTOP	BD82B65	S LJ4A	914379
Intel® BD82H61 Platform Controller Hub	B3	DESKTOP	BD82H61	S LJ4B	914380
Intel® BD82Q67 Platform Controller Hub	B3	DESKTOP	BD82Q67	S LJ4D	914397
Intel® BD82Z68 Platform Controller Hub	B3	DESKTOP	BD82Z68	S LJ4F	914416
Intel® BD82C206 Platform Controller Hub	B3	SERVER	BD82C206	S LJ4G	914417
Intel® BD82C204 Platform Controller Hub	B3	SERVER	BD82C204	S LJ4H	914418
Intel® BD82C202 Platform Controller Hub	B3	SERVER	BD82C202	S LJ4J	914419
Intel® BD82QS77 Platform Controller Hub	C1	MOBILE	BD82QS77	S LJ8B	915660
Intel® BD82QM77 Platform Controller Hub	C1	MOBILE	BD82QM77	S LJ8A	915663
Intel® BD82HM77 Platform Controller Hub	C1	MOBILE	BD82HM77	S LJ8C	915664
Intel® BD82UM77 Platform Controller Hub	C1	MOBILE	BD82UM77	S LJ8D	915665
Intel® BD82HM76 Platform Controller Hub	C1	MOBILE	BD82HM76	S LJ8E	915666
Intel® BD82HM75 Platform Controller Hub	C1	MOBILE	BD82HM75	S LJ8F	915667
Intel® BD82Q77 Platform Controller Hub	C1	DESKTOP	BD82Q77	S LJ83	915673
Intel® BD82Q75 Platform Controller Hub	C1	DESKTOP	BD82Q75	S LJ84	915674
Intel® BD82B75 Platform Controller Hub	C1	DESKTOP	BD82B75	S LJ85	915675
Intel® BD82Z75 Platform Controller Hub	C1	DESKTOP	BD82Z75	S LJ87	915677
Intel® BD82H77 Platform Controller Hub	C1	DESKTOP	BD82H77	S LJ88	915678
Intel® BD82C216 Platform Controller Hub	C1	SERVER	BD82C216	S LJ8H	915680
Intel® BD82Z77 Platform Controller Hub	C1	DESKTOP	BD82Z77	S LJC7	918608
Intel® BD82C608 Platform Controller Hub	C1	SERVER	BD82C608	S LJKF	919597
Intel® BD82C602 Platform Controller Hub	C1	SERVER	BD82C602	S LJKG	919598
Intel® BD82C606 Platform Controller Hub	C1	SERVER	BD82C606	S LJKH	919599
Intel® BD82C604 Platform Controller Hub	C1	SERVER	BD82C604	S LJKJ	919601
Intel® BD82X79 Platform Controller Hub	C1	SERVER	BD82X79	S LJN7	920099
Intel® BD82C602J Platform Controller Hub	C1	SERVER	BD82C602J	S LJNG	920240
Intel® BD82HM70 Platform Controller Hub	C1	MOBILE	BD82HM70	S JTNV	921362
Intel® BD82NM70 Platform Controller Hub	C1	MOBILE	BD82NM70	S LJTA	922754

## PCN Revision History:

**Date of Revision:**

December 17, 2014

**Revision Number:**

00

**Reason:**

Originally Published PCN