



Product Change Notification

112467 - 00

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2013. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 112467 - 00
Change Title: Intel® Xeon Phi™ Coprocessors 3120A, 3120P, 31S1P, 5110P, 5120D, 7110P, 7110X 7120D, 7120P, 7120X and 71S1P
PCN 112467-00, Product Design
Update System Manageability Controller
Code / Flash
Date of Publication: April 23, 2014

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	May 08, 2014
---	--------------

Description of Change to the Customer:

Intel will implement the following changes on Intel® Xeon Phi™ Coprocessors 3120A, 3120P, 31S1P, 5110P, 5120D, 7110P, 7110X 7120D, 7120P, 7120X and 71S1P:

- Update the SMC code in manufacturing from 1.14 to 1.16/ Flash 386.2 to 390.02

Intel strongly recommends the use of the latest MPSS with these new versions of SMC and Flash. The latest Intel® MPSS package is available for download from

<https://software.intel.com/en-us/articles/intel-manycore-platform-software-stack-mpss>.

Customer Impact of Change and Recommended Action:

Intel recommends that the customers perform a standard level of evaluation on this new software stack.

Intel will attempt to deplete pre-conversion material before shipping post-conversion material but there is a possibility of Intel shipping mixed inventory. Therefore, customers will need to manage and migrate to the post-conversion material as soon as possible.

Milestone dates are estimates and subject to change based on business and operational conditions.

Customers must use the micflash tool to update the SMC code as future updates become available with new releases of the Intel® MPSS at

<https://software.intel.com/en-us/articles/intel-manycore-platform-software-stack-mpss>

Products Affected / Intel Ordering Codes:

Product Code	Marketing Name	MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
SC7110X	7110X	924042	G65756-253	G65496-253	G65756-254	G65496-254
SC7110P	7110P	924043	G65757-253	G65496-253	G65757-254	G65496-254
SC5110P	5110P	924044	G65758-255	G65497-254	G65758-256	G65497-255
SC71S1P	71S1P	925618	G78930-253	G65496-253	G78930-254	G65496-254
SC31S1P	31S1P	925619	G78927-252	G76337-252	G78927-253	G76337-253
BC31S1P	31S1P	925620	G78927-252	G76337-252	G78927-253	G76337-253
SC7120X	7120X	927498	G65756-350	G90467-350	G65756-351	G90467-351
SC7120P	7120P	927499	G65757-350	G90468-350	G65757-351	G90468-351
SC3120A	3120A	927500	G65493-350	G65493-350	G65493-351	G65493-351
SC3120P	3120P	927501	G82474-350	G88044-350	G82474-351	G88044-351
SC5120D	5120D	927503	G61933-250	G43066-250	G61933-251	G43066-251
SC7120PEB	7120P	931158	H13647-350	G90468-350	H13647-351	G90468-351
SC5110PEB	5110P	931159	H13742-254	G65497-254	H13742-255	G65497-255
SC3120PEB	3120P	931160	H13740-350	G88044-350	H13740-351	G88044-351
SC3120AEB	3120A	931161	H13668-350	G65493-350	H13668-351	G65493-351
SC3120AIB	3120A	931162	H13708-350	G65493-350	H13708-351	G65493-351
SC7120D	7120D	932330	H16728-255	H15867-250	H16728-255	H15867-251
SC5110PKIT	5110P	932981	G65758-253	G65497-253	G65758-256	G65497-255
SC3120AKIT	3120A	932982	G65759-350	G65493-350	G65759-351	G65493-351

PCN Revision History:

Date of Revision:

April 23, 2013

Revision Number:

00

Reason:

Originally Published PCN