



# Product Change Notification

## 111272 - 01

**INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.**

**A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.**

**Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.**

**The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.**

**Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.**

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific/PRC Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2012. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at  
<http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 111272 - 01  
**Change Title:** Intel® Server Chassis P4304XXSFCN  
Intel® Server Chassis P4304XXSHCN  
Intel® Server System P4304BTLSFCN  
Intel® Server System P4304BTLSHCN  
Intel® Server System P4304BTSSFCN  
PCN 111272-01, Product Design  
Chassis Design improvement  
**Reason for Revision: Add bezel information for specific skus, Revise Description of Change and Remove SKUs no longer affected**

**Date of Publication:** October 1, 2012

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:


<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Mar 05, 2012
---	--------------

## Description of Change to the Customer:


**Reason for Revision: Add bezel information for specific skus, Revise Description of Change and Remove SKUs no longer affected**

1. Intel will implement the following changes on the Intel® Server Chassis P4304XXSFCN and P4304XXSHCN, Intel® Server System P4304BTLSFCN, P4304BTLSHCN and P4304BTSSFCN:


1.1. Improve chassis rear panel and peripheral bay design. The following are pictures of prior and post changes:




1.2. Improve chassis PCI retainer design. The following are pictures of prior and post change:




1.3. Add blue palm pad on side cover. The following are pictures of prior and post change:



1.4. Remove one front panel clip, and only keep one clip for assembly flexibility. The following are pictures of prior and post change product:



1.5. MAC address label size and location change. The following are pictures of prior and post change product:




1.6. Add two Optical Disk Drive (ODD) rails in accessory kits. The following are pictures of the two ODD rails:



2. Intel will implement following change on Intel® Server Chassis P4304XXSFCN, P4304XXSHCN and Intel® Server System P4304BTLSFCN, P4304BTSSFCN:


2.1. Improve chassis fixed front bezel assembly design. The following are pictures of prior and post change:



2.2. The post change P4304XXSHCN, P4304XXSFCN, P4304BTLSFCN, P4304BTSSFCN only support the spare Bezel with fixed drive (no door) FUPBEZLFIX2 (MM# 925750).

3. Intel will implement the following change on Intel® Server Chassis P4304XXSHCN and Intel® Server System P4304BTLSHCN:

3.1. Improve chassis hot-swap front bezel assembly design. The following are pictures of prior and post change:



3.2. The post change P4304XXSHCN, P4304XXSFCN, P4304BTLSFCN and P4304BTSSFCN only support the spare Bezel with hot-swap drive (with door) FUPBEZELHSD2 (MM# 925749).

### **Customer Impact of Change and Recommended Action:**

No adverse customer impact is expected from these changes. Customers are expected to evaluate potential impact as updated product becomes available.

Customers who place future bezel spare orders for post change server chassis and server systems need to use the new Bezel order codes. See details in this PCN.



## Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change TA	Post Change TA
P4304XXSFCN	911754	G15844-005	G15844-006
P4304XXSHCN	911765	G21447-004	G21447-005
P4304BTLSHCN	912775	G22759-003	G22759-004
P4304BTLSFCN	912776	G22757-003	G22757-004
P4304BTSSFCN	912777	G22760-003	G22760-004

## Products no longer affected in this PCN:

Product Code	MM#
P4304XXSFCNNA	907811
P4304XXSHCNNA	907812
P4304BTLSFCNNA	908252
P4304BTLSHCNNA	907886
P4304BTSSFCNNA	908785

## PCN Revision History:

**Date of Revision:**

February 6, 2012

October 1, 2012

**Revision Number:**

00

01

**Reason:**

Originally Published PCN

Add bezel information for specific skus, Revise Description of Change and Remove SKUs no longer affected