



Product Change Notification

108199 - 02

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jcb.ijkk@intel.com

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 108199 - 02
Change Title: DQ35JO, PCN 108199-02, Product Design, BIOS Update for Yorkfield CPU support, implement enhanced BIOS features and adding alternate component to improve manufacturability, Reason for Revision: BIOS revision change to include additional updates.
Date of Publication: April 11, 2008

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Apr 24, 2008
---	--------------

Description of Change to the Customer:

Reason for Revision: BIOS revision change to include additional updates.

Update BIOS to JOQ3510J.86A.0865

Please refer to the release notes posted at

<http://developer.intel.com/products/motherboard/DQ35JO/tools.htm>

The BIOS will incorporate the new Intel® Rapid Recovery Technology BIOS feature.

A second source audio jack from E-Move will be added to insure adequate supply.

Customer Impact of Change and Recommended Action:

It is recommended that customers evaluate this new BIOS to ensure a smooth transition.

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. Intel is not recommending additional qualification of these changes on platforms received from Intel. This change is not expected to cause a change to the Microsoft* Windows* operating system's software driver stack. No expected OS image change.

Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change AA	Post Change AA
BLKDQ35JOE	888802	D82085-801	D82085-802
BOXDQ35JOE	888804	D82085-801	D82085-802

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
March 10, 2008	00	Originally Published PCN
April 1, 2008	01	BIOS Version Change
April 11, 2008	02	BIOS revision change to include additional updates.