



Product Change Notification

110942 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2011. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 110942 - 00
Change Title: Intel(R) Server Chassis P4304XXSFCN and P4304XXSHCN, Intel(R) Server System P4304BTLSFCN, P4304BTLSHCN, P4304BTSSFCN, R1304BTLSFAN, R1304BTLSHBN and R1304BTSSFAN, PCN 110942 - 00, Label, Regulatory Label Change,
Date of Publication: August 11, 2011

Key Characteristics of the Change:

Label

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Aug 26, 2011
---	--------------

Description of Change to the Customer:

Intel will implement the following changes on the Intel® Server System R1304BTLSFAN, R1304BTLSHBN, R1304BTSSFAN, P4304BTLSFAN, P4304BTLSHBN and P4304BTSSFAN, Intel® Server Chassis P4304XXSFAN and P4304XXSHBN:

1. The label on the chassis will have two changes: the ETL/GS mark will be changed to a Nemko mark and a Ukraine mark will also be added. The label part number will change from G19891-001 to G19891-003.



This is the label of G19891-001




This is the new label of G19891-003

- The label on the outer package will have two changes: the ETL/GS mark will change to a Nemko mark and a Ukraine mark will also be added. The label part number will change from G21162-001 to G21162-002.

This is the old label of G21162-001



This is the new label of G21162-002



- The Country Of Origin (COO) label for different countries will change from P4 to PXXXX for the Intel® Server Chassis P4304XXSFAN and P4304XXSHBN and Intel® Server System P4304BTLSFAN,

P4304BTLSHBN and P4304BTSSFAN. The Country Of Origin (COO) label for different countries will change from R1 to RXXXX for the Intel® Server System R1304BTLSFAN, R1304BTLSHBN and R1304BTSSFAN. The following picture is the old COO label.



The following picture is the new label.



Customer Impact of Change and Recommended Action:

Customers may need to determine the need for the changing of the label marking on their products before they are exported.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change Product Code	Pre Change MM#

R1304BTLSHBN	911688	R1304BTLSHBN	911688
R1304BTLSFAN	911698	R1304BTLSFAN	911698
R1304BTSSFAN	911709	R1304BTSSFAN	911709
R1304BTLSHBNNNA	907658	R1304BTLSHBNNNA	907658
R1304BTLSFANNA	907775	R1304BTLSFANNA	907775
R1304BTSSFANNA	907569	R1304BTSSFANNA	907569
P4304BTLSHCNNA	907886	P4304BTLSHCNNA	907886
P4304BTLFCNNA	908252	P4304BTLFCNNA	908252
P4304BTLSHCN	912775	P4304BTLSHCN	912775
P4304BTLFCN	912776	P4304BTLFCN	912776
P4304XXSFCN	911754	P4304XXSFCN	911754
P4304XXSHCN	911765	P4304XXSHCN	911765
P4304BTSSFCN	912777	P4304BTSSFCN	912777
P4304XXSFCNNA	907811	P4304XXSFCNNA	907811
P4304XXSHCNNA	907812	P4304XXSHCNNA	907812
P4304BTSSFCNNA	908785	P4304BTSSFCNNA	908785

PCN Revision History:

Date of Revision:

August 11, 2011

Revision Number:

00

Reason:

Originally Published PCN