



Product Change Notification

Change Notification #: 115490 - 00
Change Title: Intel® Compute Stick STK2m3W64CC,
Intel® Compute Stick STK2m3W64CCL,
Intel® Compute Stick STK2m364CC,
Intel® Compute Stick STK2m364CCL,
PCN 115490-00, Product Design,
Firmware Update (all SKUs) and Software
Update for STK2M3W64CC and
STK2M3W64CCL
Date of Publication: April 27, 2017

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	May 12, 2017
---	--------------

Description of Change to the Customer:

The Intel® Compute Stick SKUs listed in the products affected table below will have the following changes.

1. The current Windows 10 Home operating system image will be updated to Windows 10 Home Build 1703 along with driver updates for SKUs STK2M3W64CC and STK2M3W64CCL.
2. The BIOS will be updated from CCSKLM30.86A.0043 to CCSKLM30.86A.0050 for all SKUs. A complete list of the BIOS changes can be found in the BIOS release notes. The BIOS update and release notes can be found at <http://downloadcenter.intel.com>

Customer Impact of Change and Recommended Action:

It is recommended that customers evaluate this new BIOS to ensure a smooth transition. This change has been thoroughly evaluated to ensure that there are no quality or reliability implications to our customers. Intel validation of a new board revision does not include testing with older versions of BIOS.

Milestone dates are estimates and subject to change based on business and operational conditions.

Customer can expect to receive mixed inventory until current inventory levels are depleted.

Please contact your local Intel Field Sales Rep if you have any further questions about these changes.

Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change SA	Pre Change AA	Post Change SA	Post Change AA
BOXSTK2M3W64CC	944712	H87908-208	H89289-503	H87908-209	H89289-504
BLKSTK2M364CC	944721	H87911-206	H89291-503	H87911-207	H89291-504
BOXSTK2M3W64CCL	947055	H97102-205	H89289-503	H97102-206	H89289-504
BLKSTK2M364CCL	947057	H97103-205	H89291-503	H97103-206	H89291-504

PCN Revision History:

Date of Revision:
April 27, 2017

Revision Number:
00

Reason:
Originally Published PCN



Product Change Notification

115490 - 00

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2017. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.